

Inspection Photos

ID: 478058

Operator: OGRIS OPERATING LLC

Inspection Date: 7/22/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing west at the road to the production facility. There is erosion along this area and the round rock has washed out. Angular rock would be better for erosion control..



Inspection Photos



Photo 2. There is sediment that has filled in along the road side from the production facility.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 3. Facing northwest toward the tank battery. There are oil stained soils in this area that must be cleaned up.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

ID:478058 | Date: 7/22/2024

Inspection Photos



Photo 4. There is oily fluids inside this plastic container which has no netting to prevent wildlife entry.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 5. There is oily fluids in the secondary containment that has spilled over onto the ground. Additionally netting must be installed to prevent wildlife entry.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

ID:478058 | Date: 7/22/2024

Inspection Photos



Photo 6. There is a bucket of oily fluid at the northeast side of the tank battery that needs to be disposed and contained in secondary containment with netting.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 7. There is trash and empty cans in the containment that need to be disposed.



Inspection Photos



Photo 8. The netting on the open top tank is not maintained.



Inspection Photos



Photo 9. Facing northeast overlooking the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

ID:478058 | Date: 7/22/2024