

# Inspection Photos

ID: 312120

Operator: XTO ENERGY INC

Inspection Date: 7/22/2024

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing west toward the location. The bottom portion of the location needs to be reclaimed with proper recontouring and stabilization.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



## Inspection Photos



**Photo 2.** Facing southwest at the location.





## Inspection Photos



**Photo 3.** Facing toward the open pit which is still in process of remediation.





## Inspection Photos



**Photo 3.** Facing southeast toward the soil pile. There are undesirable weeds growing throughout this area that will need to be controlled.





## Inspection Photos



**Photo 4.** Facing southwest at the location.





## Inspection Photos



**Photo 5.** There is pipe and wire shown at red arrows that need to be removed..





## Inspection Photos



**Photo 7.** Facing toward the open pit at the base of the cut slope..





## Inspection Photos



**Photo 8.** North side of the location facing southeast.





## Inspection Photos



**Photo 9.** North side of the location facing east. The bottom portion of the location needs to be reclaimed with proper recontouring and stabilization.

