

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/25/2024

Submitted Date:

07/27/2024

Document Number:

708904234

FIELD INSPECTION FORM

Loc ID 335553 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Operator Information:

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

16 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
417380	WELL	DG	02/01/2018	GW	045-19496	VALLEY FARMS I1H	DG

General Comment:

[CECMC Inspection Report Summary](#)
On 07/25/2024 at approximately 10:00 hours, I, Compliance Specialist, Wayne Smelser Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC Valley Farms I Pad. Location # 335553 in Garfield County Colorado.
Location is within High Priority/Density/Black Bear Habitat areas & in close proximity to NSO Habitat area & Bald Eagle Roost Site.
Location is approximately 230 yards from Mineota Ditch & 296 yards from Divide Creek.
Location is within Rule 411a Surface Water Internal & Intermediate Buffers & in close proximity to Rule 411b Generalized Intermediate & External Buffers.
While there, I observed P & A operations on the VALLEY FARMS I1H well.

This is a summary of inspection report.

Limited inspection due to ongoing P & A operations

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	OTHER		
Comment:	Rig sign at intersection of CR 311 & start of lease road		
Corrective Action:			Date:
Type	OTHER		
Comment:	Rig sign at entrance to location		
Corrective Action:			Date:

Emergency Contact Number:		
Comment:	911/970-285-9377	
Corrective Action:		Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Other	# 1		
Comment:	Rig tank		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Workover rig		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Accumulator		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Cement truck		
Corrective Action:			Date:
Type: Other	# 2		
Comment:	500 bbl frac tanks		
Corrective Action:			Date:
Type: Other	# 1		

Comment: Pump truck			
Corrective Action:			Date:
Type: Other	# 1		
Comment: Bobtail			
Corrective Action:			Date:
Type: Other	# 1		
Comment: Rig pump			
Corrective Action:			Date:
Type: Other	# 1		
Comment: Wireline truck			
Corrective Action:			Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 417380 Type: WELL API Number: 045-19496 Status: DG Insp. Status: DG

Cement

Cement Contractor

Contractor Name: Duco

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____

Cement Volume (sx): _____

Good Return During Job: _____

Cement Type: _____

Comment: Observed crew pumping 182 sacks for casing shoe plug & then observed rig crew tripping out of the hole & rigging down for the day.

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Limited inspection due to ongoing P & A operations](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Limited inspection due to ongoing P & A operations	smelserw	07/27/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708904235	Inspection 708904234 photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6641461