

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DIXON A Pad

Location #: 335550



Photo # 3239 From entrance to location



Photo # 3240 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DIXON A Pad

Location #: 335550



Photo # 3241 Location



Photo # 3242 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DIXON A Pad

Location #: 335550



Photo # 3243 Location



Photo # 3244 Location

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DIXON A Pad

Location #: 335550



Photo # 3245 Unmarked deadman



Photo # 3246 Same unmarked deadman from a different angle

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DIXON A Pad

Location #: 335550



**Photo # 3247 Unused equipment/ECD disconnected & not in use**



**Photo # 3248 Dead weeds/debris near wellheads & chemical tank that is causing a fire hazard**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DIXON A Pad

Location #: 335550



**Photo # 3249 Dead weeds/debris near wellheads & chemical tank that is causing a fire hazard**



**Photo # 3250 Dead weeds/debris near wellheads & chemical tank that is causing a fire hazard**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DIXON A Pad

Location #: 335550



**Photo # 3251 Wellhead cellar lacks wildlife egress/does not comply with CECMC wildlife rules**



**Photo # 3252 Wildlife egress damaged/needs maintenance**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DIXON A Pad

Location #: 335550



**Photo # 3253 Cellar not properly covered/wildlife & personnel hazard**



**Photo # 3254 Debris**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DIXON A Pad

Location #: 335550



Photo # 3255 Damaged hoses/debris



Photo # 3256 PRV vent line does not comply with CECMC pressure safety device rules

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DIXON A Pad

Location #: 335550



Photo # 3257 PRV vent line cap damaged/PRV vent line does not comply with CECMC pressure safety device rules




Photo # 3258 Tank label contains inaccurate info/does not comply with CECMC rules

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DIXON A Pad

Location #: 335550



**Photo # 3259 Tank label contains inaccurate info/does not comply with CECMC rules**