

Inspection Photos
Location Name: Bullard 2
Location ID: 320234



Pic 1 unable to access wellhead due to locked landowner gate



Pic 2 GMR

Inspection Photos
Location Name: Bullard 2
Location ID: 320234



Pic 3 Separator



Pic 4 Buried vault tank

Location ID: 320234



Pic 5 Oil tank