

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/23/2024

Submitted Date:

07/29/2024

Document Number:

693807509**FIELD INSPECTION FORM**Loc ID 399572 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10453Name of Operator: PARADOX UPSTREAM LLCAddress: 500 DALLAS ST SUITE #1650City: HOUSTON State: TX Zip: 77002**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|--------------|-----------------------------|---------------------------------|
| Roberts, Jake | | jroberts@americanhelium.us | All Inspections |
| Browning, Chuck | 970-433-4139 | chuck.browning@state.co.us | Field Inspector |
| Hankins, Neil | 970-428-2742 | nhankins@americanhelium.us | All Inspections |
| Labowskie, Steve | | steve.labowskie@state.co.us | |
| Gavito, Danielle | | dgavito@americanhelium.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 275967 | WELL | TA | 01/17/2005 | GW | 113-06173 | HC MEX 14-13-44-15 | TA |

General Comment:

ECMC staff performed a routine field inspection on 7/23/2024.
Issues were found requiring corrective action. See inspection text and photos for details.

Location**Lease Road:**

| | | | |
|--------------------|--------|-------|--|
| Type | Access | | |
| comment: | | | |
| Corrective ActionL | | Date: | |
| Type | Main | | |
| comment: | | | |
| Corrective ActionL | | Date: | |

Overall Good: ☒**Signs/Marker:**

| | | | |
|--------------------|----------|-------|--|
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | |
|--------------------|------------------------------------------------|------------------|
| Comment: | 866-775-8385 Wrong Emergency contact number | |
| Corrective Action: | Install sign to comply with Rule 605.d. | Date: 08/30/2024 |

Overall Good: ☒**Spills:**

| Type | Area | Volume | | |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|-------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | Panel fence | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | |
|--------------------------|-----|-------|-----------------|
| | | | corrective date |
| Type: Bradenhead | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Deadman # & Marked | # 4 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | | | | | | | | |
|----------------------|--------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-----------------------------------------------------------|-----------|-----------|----|---------------|----|------------|
| Facility ID: | 275967 | Type: | WELL | API Number: | 113-06173 | Status: | TA | Insp. Status: | TA | |
| Idle Well | | | | | | | | | | |
| Purpose: | | <input type="checkbox"/> Shut In | | <input checked="" type="checkbox"/> Temporarily Abandoned | | Reminder: | | | | |
| Comment: | | <div>Last MIT to maintain SI/TA status 12/7/2015. Well TA longer than 6 months with no Form 4 submitted</div> | | | | | | | | |
| Corrective Action: | | <div>Well is overdue for Mechanical Integrity Test (MIT) MIT require 10 day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to plug well. Well can only be returned to SI status if it has produced (without mechanic intervention) within 2 years per Rule 417.c. See NOAV doc#403161100 dated 09/09/2022. CA date of 10/09/2022 not completed.</div> | | | | | | Date: | | 10/09/2022 |

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

| | | | | | | |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| Compaction | Pass | Compaction | Pass | | | |

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| | | |
|--------------|-----------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Document Num | Description | URL |
| 693807510 | Inspection photos 7/23/2024 | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6642317 |