

Construction and Stormwater Inspection

Date: 7/18/24

Operator: Kerr McGee Oil & Gas Onshore LP - 47120

Location ID: 486289

Inspection Document #: 713900784

Weld County, CO

Logan Hansen
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Clover 2-29HZ
Location ID: 486289



Photo 1. The photo was taken at the entrance to the well location facing Southwest. The photo illustrates the operator location sign and document mailbox.

Note - At the time of inspection the Form 2A was not in the mailbox onsite.



Photo 2. The photo was taken at the entrance to the well location facing South. The photo illustrates the access road is using an existing access road.

Inspection Photos
Location Name: Clover 2-29HZ
Location ID: 486289



Photo 3. The photo was taken at the well location facing East. The photo illustrates apparent sediment traps under construction.



Photo 4. The photo was taken at the well location facing North. The photo illustrates the topsoil salvage in process.

Note - Indicated by the Red arrow the photo also illustrates use of a water truck for dust suppression.

Inspection Photos
Location Name: Clover 2-29HZ
Location ID: 486289



Photo 5. The photo was taken at the well location facing North. The photo illustrates topsoil salvage in process and location temporary perimeter stormwater control ditch and berm.



Photo 6. The photo was taken at the well location facing West. The photo illustrates the location boundary ditch and berm.

Note - Large populations of Scotch thistle were in the reference areas surrounding the location and should be considered during construction and production at the facility in the future.

Inspection Photos
Location Name: Clover 2-29HZ
Location ID: 486289



Photo 7. The photo was taken at the well location facing South. The photo illustrates a location sediment trap, with sides that appear to be appropriate and a protected outlet.

Inspection Photos
Location Name: Clover 2-29HZ
Location ID: 486289



ECMC
240° SW
7/18/24, 10:17 AM

Photo 8. The photo was taken at the well location facing Southwest. The photo illustrates a ditch with flowing water that has been diverted around the new location.



ECMC
125° SE
7/18/24, 10:18 AM

Photo 9. The photo was taken at the well location facing Southeast. Refer to the comment for photo 8.



Inspection Photos
Location Name: Clover 2-29HZ
Location ID: 486289



Photo 10. The photo is Copernicus imagery dated 7/4/24. The photo illustrates the location has yet to start construction.

Inspection Photos
Location Name: Clover 2-29HZ
Location ID: 486289



Photo 11. The photo is Copernicus imagery dated 7/11/24. The photo illustrates the location has begun construction prior to the posted start date of 7/15/24.