

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/23/2024

Submitted Date:

07/29/2024

Document Number:

697602408**FIELD INSPECTION FORM**Loc ID 333171 Inspector Name: Ahmadian, Alexander On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Brown, Kari		kari.oakman@state.co.us	
Peterson, John		jpeter@kpk.com	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
,		cogcc@kpk.com	All Inspections
Watzman, Ross	303-825-4822	rwatzman@kpk.com	
Anderson, Laurel		laurel.anderson@state.co.us	
Graber, Nikki		nikki.graber@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241909	WELL	PR	10/01/2023	OW	123-09700	MOSER 1-A	EI
481067	SPILL OR RELEASE	CL	07/12/2022		-	Moser 1A	EI

General Comment:

This is an environmental inspection to document backfill of Spill ID 481067/Remediation Project No 23510. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Environmental**Spills/Releases:**

Type of Spill: _____

Estimated Spill Volume: _____

Comment: PER CA Document #689501448: "Remedial excavation for Spill ID 481067/Remediation Project No 23510 has been backfilled. The last approved Supplemental Form 27 for this remediation project was received on May 12, 2022 (Doc # 403047594). Operator is past due on quarterly reporting. This location was included in NOAV # 403513701 for violation of Rule 913.e.(3). Associated well (Moser 1A) was producing at the time of inspection. Note: Excavation was emergency backfilled to allow Operator to address wellhead integrity issues. ECMC environmental staff did not grant approval for backfill. ECMC environmental staff was not given notification for excavation backfill."

Corrective Action: Operator shall immediately submit a Form 27 for Remediation Project No 23510 with any analytical data not previously submitted and a specific workplan and timeline to address any impacts remaining in-situ.

Date: 08/10/2022

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697602409	Photolog	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6643461