

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/18/2024

Submitted Date:

07/23/2024

Document Number:

696205997**FIELD INSPECTION FORM**Loc ID 430926 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: ☐**Operator Information:**

ECMC Operator Number: 3104

Name of Operator: ANSCHUTZ EXPLORATION CORP

Address: 555 17TH ST STE 2400

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

2 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Organ, Lindsey	7206391235	lindsey.organ@aec-denver.com	Compliance Specialist

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
430926	LOCATION	AC			-	BHR O23-397	RI

General Comment:

On July 18, 2024, Reclamation Specialist Trujillo conducted an inspection at Anschutz Exploration Corp's BHR O23-397 Location Location in Rio Blanco County, Colorado.

Location is Fee Surface, with Fed Minerals.

Location is within the following High Priority Habitats: Aquatic Sportfish Management Waters, Greater Sage Grouse Priority Habitat Management Area, Elk Severe Winter Range, Elk Winter Concentration Area, Mule Deer Winter Concentration Area, Pronghorn Winter Concentration Area.

This inspection is a follow-up to #696205879 to document compliance with the following corrective actions:
-Spill Cleanup

It was observed in this inspection that the spill identified in Inspection #696205879 have not been cleaned- corrective actions remain outstanding.

Refer to the "Location" section of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspection that have not been addressed are still applicable.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: 1-888-696-1300

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
Comment: See "Comment #1" at the end of this report.				
Corrective Action: Clean up spills/releases per Rule 912.a. Comply with Rule 906 litte "a" though "d" regarding management of non-E&P waste. Clean/Remediate impacts to Table 915-1 standards.			Date:	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type:	#		corrective date
Comment: See "Comment #1" at the end of this report			
Corrective Action: Comply with Rule 608.e- All Production Facilities, valves, pipes, fittings, and vessels will be securely fastened or sealed, inspected at regular intervals, and maintained in good mechanical condition.		Date:	07/26/2024

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 430926 Type: LOCATION API Number: - Status: AC Insp. Status: RI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
Inspection #696205879 observed stained soil due to spills on the west end of the Location and at the base of the methanol tank on the southwest end of the Location. It was observed in this inspection that the stained soils on the west end of the Location have not been cleaned/remediated. Additionally, a lead was observed at the pipe above the stained soils. Operator on site was made aware of the leaking pipe. Though work to clean up the spills at the methanol tank is evident, cleanup has been insufficient and stained soils remain evident at the base, and seemingly under the containment BMP. Spills previously observed at the dumpster/cage appear to have been cleaned.	trujilloam	07/23/2024

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403863151	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6635869
696205998	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6635865