

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/02/2024

Submitted Date:

07/23/2024

Document Number:

713400192

FIELD INSPECTION FORM

 Loc ID: 324270
 Inspector Name: Popejoy, Dusty
 On-Site Inspection:
 2A Doc Num:
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 ECMC Operator Number: 10770
 Name of Operator: VISION ENERGY LLC
 Address: P O BOX 370
 City: IGNACIO State: CO Zip: 81137
Findings:

- 9 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
ENERGY, VISION		mollieo@maralexinc.com	
ENERGY, VISION		mrine20@maralexinc.com	
Toews, Wesley		wtoews@blm.gov	
ENERGY, VISION		pbechtolt@maralexinc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
266869	WELL	SI	09/01/2009	CBM	045-09853	SOUTH SHALE RIDGE 1-14H	SI

General Comment:[CECMC Inspection Report Summary](#)

On 7/2/2024 at approximately 15:00, Compliance Inspector Dusty Popejoy conducted an on-site inspection at VISION ENERGY LLC SOUTH SHALE RIDGE-68S98W/14NENE at Location ID # 324270 in Garfield County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

During the inspection, the following compliance issues were observed:

Signs/Marker:

- 1) Tank label does not meet required information with a CA date of 8/23/2024

Housekeeping:

- 2) Weeds and undesirable plant species present across entire location with a CA date of 8/23/2024
- 3) Debris on location with a CA date of 8/23/2024

Earth Berm:

- 4) Berm permeability is inadequate due to weed growth in berm with a CA date of 8/23/2024

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

Any Corrective Actions from previous Inspections are still applicable.

Location			
Lease Road:			
Type	Access		
comment:	Access		
Corrective Action			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Tank label does not meet required information.		
Corrective Action:	Comply with CECMC labeling rules.		Date: 08/23/2024
Emergency Contact Number:			
Comment:	911/970-858-8550		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	DEBRIS		
Comment:	Debris present across entire location, refer to photos.		
Corrective Action:	Comply with CECMC debris rules.		Date: 08/23/2024
Type	WEEDS		
Comment:	Weeds and undesirable plant species present across entire location, refer to photos.		
Corrective Action:	Comply with CECMC weed control rules.		Date: 08/23/2024
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Gas Meter Run	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Bradenhead valve is accessible.		
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:

Type: Pump Jack	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
	1		FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Berm permeability is inadequate due to weed growth in berm, refer to photos.			
Corrective Action:	Comply with CECMC weed control rules.			Date: 08/23/2024

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 266869 Type: WELL API Number: 045-09853 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action:

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						
Waddles						
Berms						
		Compaction				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403863540	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6636223
713400193	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6636219