

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/19/2024

Submitted Date:

07/23/2024

Document Number:

713400208**FIELD INSPECTION FORM**Loc ID 420164 Inspector Name: Popejoy, Dusty On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1700 LINCOLN ST STE 3950City: DENVER State: CO Zip: 80203**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**15 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, LARAMIE		cogccnotifications@laramie-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
420160	WELL	PR	07/01/2020	GW	077-10119	Kimball Creek 23-412D-995	PR
420161	WELL	PR	08/01/2020	GW	077-10120	Kimball Creek 23-210D-995	PR

General Comment:CECMC Inspection Report Summary

On 7/19/2024 at approximately 14:52, Compliance Inspector Dusty Popejoy conducted an on-site inspection at LARAMIE ENERGY LLC Kimball Creek Pad/23-4C-995 at Location ID #420164 in Mesa County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

During the inspection, the following compliance issues were observed:

Tank and Berms:

1- Open ended load lines with a CA date of 8/2/2024

Signs/Marker

2- Methanol tank label is illegible and needs replaced with a CA date of 8/23/2024

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

Any Corrective Actions from previous Inspections are still applicable.

Location

Lease Road:			
Type	Access		
comment:	Access		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	OTHER		
Comment:	Sign at entrance to location.		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical tank.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Methanol tank label is illegible and needs replaced, refer to photos.		
Corrective Action:	Comply with CECMC labeling rules.	Date:	08/23/2024
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	911/1-800-891-6191		
Corrective Action:			Date: _____

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Hog panels.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	

Type: Ancillary equipment	# 1	
Comment:	Chemical tank.	
Corrective Action:		Date:
Type: Bradenhead	# 2	
Comment:	All Bradenhead valves are accessible.	
Corrective Action:		Date:
Type: Gas Meter Run	# 2	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 2	
Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 2	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		,
Comment:	Open ended load line.				
	Telemetry on tank.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Centralized containment.				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		,
Comment:	Open ended load lines, refer to photos.				
	Telemetry on tanks.				
Corrective Action:	All load lines will be capped or plugged.				Date: 08/02/2024

Paint

Condition	Adequate
-----------	----------

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:	Centralized containment.				
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	420160	Type:	WELL	API Number:	077-10119	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well.								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	420161	Type:	WELL	API Number:	077-10120	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well.								
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				
Ditches						
		Culverts				
		Compaction				
		Ditches				
Compaction						
Gravel						
Berms						

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403863618	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6636325
713400209	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6636318