

# Inspection Photos

API: 071-07915

Operator: WAPITI OPERATING LLC

Inspection Date: 7/29/2024

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing west along the access road. There is erosion occurring on this section of the road which has been problematic with vehicle rutting and erosion. This section to the red arrow needs to be crowned with roadbase and gravel.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:071-07915 | Date: 7/29/2024



## Inspection Photos



**Photo 2.** Stormwater is beginning to create a deep rill and stormwater is not being diverted off the road.





## Inspection Photos



**Photo 3.** Facing back east. There is erosion occurring on this section of the road which has been problematic with vehicle rutting and erosion. This section of the road needs to be crown with roadbase and gravel.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



## Inspection Photos



**Photo 4.** Facing west along the access road. The remainder of the road is maintained.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



## Inspection Photos



**Photo 5.** Facing southwest toward the location.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources