

Inspection Photos

API: 071-09051

Operator: WAPITI OPERATING LLC

Inspection Date: 7/29/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northeast along the access road. There is a long stretch of road with no stormwater diversion which is concentrating a lot of flow to the area in the following pictures.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-09051 | Date: 7/29/2024

Inspection Photos



Photo 2. Facing southeast along the access road. There is erosion along the roadside which needs BMP's to control erosion. Tip: Rocks could be utilized to create check dam structures for erosion control.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-09051 | Date: 7/29/2024

Inspection Photos



Photo 3. Stormwater is flowing across the road instead of toward the culvert at red arrow.



Inspection Photos



Photo 4. The culvert does not have outlet protection and erosion is occurring in this area.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-09051 | Date: 7/29/2024

Inspection Photos



Photo 5. Facing toward the wellsite.

