

Inspection Photos

API: 071-06819

Operator: WAPITI OPERATING LLC

Inspection Date: 7/29/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southeast along the main access road. Noxious weeds have been controlled.



Inspection Photos



Photo 2. Facing northeast along the access road. Sediment has filled into the diversion ditch and stormwater is going back onto the road causing erosion..



Inspection Photos



Photo 3. Facing back down the road at the wellsite. There is erosion occurring down the road causing erosion. A berm would help divert the water off the road to prevent erosion.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-06819 | Date: 7/29/2024

Inspection Photos



Photo 4. Facing toward the wellsite.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources