

State of Colorado  
Energy & Carbon Management Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

ECMC RECEPTION

Receive Date:

01/22/2024

Document Number:

403617320

## Off-Location Flowline

The Flowline Report, Form 44, shall be submitted to register, report realignment, report removal from service, provide pre-abandonment notices, or report abandonment of Off-Location Flowlines, Flowline Systems, Produced Water Transfer Systems, or Crude Oil Transfer Lines or Systems as required by the 1100 Series Rules. The Form 44 shall also be submitted to register, report realignment, or report abandonment of Domestic Taps, and to report Grade 1 Gas Leaks from Flowlines per Rules 610 and 906.

## Operator Information

ECMC Operator Number: 10633 Contact Person: James Miller  
Company Name: CRESTONE PEAK RESOURCES OPERATING LLC Phone: (720) 984-7460  
Address: 555 17TH STREET SUITE 3700 Email: jmiller@civiresources.com  
City: DENVER State: CO Zip: 80202  
Is the Operator a Tier One member of the Utility Notification Center of Colorado (CO811) that participates in Colorado's One Call notification system? Yes ☒ No ☐

## OFF LOCATION FLOWLINE

## FLOWLINE ENDPOINT LOCATION IDENTIFICATION

Location ID: 332731 Location Type: Production Facilities  
Name: FEDERAL-63N65W Number: 10NWNW  
County: WELD  
Qtr Qtr: NWNW Section: 10 Township: 3N Range: 65W Meridian: 6  
Latitude: 40.246077 Longitude: -104.654907

## Description of Corrosion Protection

Crestone pipelines are covered in a protective external coating. Flowlines are subject to thorough inspections and fabrication standards during installation to minimize coating and pipe defects. Crestone maintains a chemical program to reduce internal corrosion. If a flowline is found to lack integrity, Crestone will investigate, report, and remediate any spills in accordance with the 900 series rules.

## Description of Integrity Management Program

Crestone flowlines are pressure tested prior to placing flowlines into service. Flowlines are tested on an annual basis in accordance with COGCC 1104 series rules. If a flowline is found to lack integrity, Crestone will investigate the root cause, as well as report and remediate any spills in accordance with the 900 series rules. All repairs will be completed in accordance with COGCC 1102 Series rules.

Description of the construction method used for public by-ways, road crossings, sensitive wildlife habitats, sensitive areas, and natural and manmade watercourses (i.e., open trench, bored and cased, or bored only), if applicable.

N/A

## FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 473114 Flowline Type: Wellhead Line Action Type:

## OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

**Flowline Start Point Location Identification**

Location ID: 336714 Location Type: Well Site ☐  
Name: FEDERAL-63N65W Number: 10SENW  
County: WELD No Location ID  
Qtr Qtr: SEnw Section: 10 Township: 3N Range: 65W Meridian: 6  
Latitude: 40.242490 Longitude: -104.653190  
Equipment at Start Point Riser: Well

**Flowline Description and Testing**

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.000  
Bedding Material:  Date Construction Completed: 08/25/1993  
Maximum Anticipated Operating Pressure (PSI):  Testing PSI:   
Test Date:

**OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification**

Date: 09/15/2023

**Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:**

The flowline serving the FEDERAL 22-10 (05-123-17096) will be removed in its entirety via the open trench method. Once the flowline is removed, the trench will be backfilled and the land surface will be graded.

**FLOWLINE FACILITY INFORMATION**

Flowline Facility ID: 473113 Flowline Type: Wellhead Line Action Type: Abandonment Verification

**OFF LOCATION FLOWLINE REGISTRATION**

Equipment at End Point Riser: Separator

**Flowline Start Point Location Identification**

Location ID: 336714 Location Type: Well Site ☐  
Name: FEDERAL-63N65W Number: 10SENW  
County: WELD No Location ID  
Qtr Qtr: SEnw Section: 10 Township: 3N Range: 65W Meridian: 6  
Latitude: 40.242490 Longitude: -104.653190  
Equipment at Start Point Riser: Well

**Flowline Description and Testing**

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.000  
Bedding Material: Native Materials Date Construction Completed: 10/13/1995  
Maximum Anticipated Operating Pressure (PSI): 260 Testing PSI:   
Test Date:

**OFF LOCATION FLOWLINE Abandonment Verification**

Date: 11/09/2023

**Abandonment Verification**

The abandoned Off-Location Flowline was located within the jurisdiction(s) of the following local government(s).

(No Jurisdiction)

**Description of Abandonment Verification:**

The flowline serviced the FEDERAL 12-10 (05-123-17136). The flowline was originally supposed to be removed, but due to co-location was abandoned in place as per Rule 1105.d. See attached exhibit for third party verification, ECMC correspondence, and flowline path exhibit.

**FLOWLINE FACILITY INFORMATION**

Flowline Facility ID: 473115 Flowline Type: Wellhead Line Action Type: Abandonment Verification

**OFF LOCATION FLOWLINE REGISTRATION**

Equipment at End Point Riser: Separator

**Flowline Start Point Location Identification**

Location ID: 332718 Location Type: Well Site ☐  
Name: ARISTOCRAT ANGUS-63N65W Number: 10NENW  
County: WELD No Location ID  
Qtr Qtr: NENW Section: 10 Township: 3N Range: 65W Meridian: 6  
Latitude: 40.245287 Longitude: -104.651707

Equipment at Start Point Riser: Well

**Flowline Description and Testing**

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.000  
Bedding Material: Native Materials Date Construction Completed: 02/05/1995  
Maximum Anticipated Operating Pressure (PSI): 140 Testing PSI:  
Test Date:

**OFF LOCATION FLOWLINE Abandonment Verification**

Date: 11/09/2023

**Abandonment Verification**

The abandoned Off-Location Flowline was located within the jurisdiction(s) of the following local government(s).

(No Jurisdiction)

**Description of Abandonment Verification:**

The flowline serving the Aristocrat 21-10C (05-123-18775) was removed in its entirety via the open trench method. Once the flowline was removed, the trench was backfilled and the land surface graded.

**OPERATOR COMMENTS AND SUBMITTAL**

Comments

Form 44 filed to report POST-ABANDONMENT verification. The following flowline was abandoned in place:  
12317136\_FL: serviced Aristocrat Angus Federal 12-10 (05-123-17136)  
Pressure test attached.  
Third party verification attached.  
Flowline path exhibit attached.  
ECMC correspondence attached.  
The 12317136\_FL was abandoned in place and does not have any associated spill/releases reported on a Form 19.

The following flowline(s) were removed:  
12318775\_FL: serviced Aristocrat Angus Federal 21-10C (05-123-18775)

Updated GIS data attached.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct and complete.  
Signed: \_\_\_\_\_ Date: 01/22/2024 Email: flowlines@civiresources.com

Print Name: Stephany Olsen Title: Sr. Regulatory Analyst

Based on the information provided herein, this Flowline Report complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved:  \_\_\_\_\_ Director of ECMC Date: 7/30/2024

## **CONDITIONS OF APPROVAL, IF ANY LIST**

**COA Type**

**Description**

### **ATTACHMENT LIST**

**Att Doc Num**

**Name**

403617320	Form44 Submitted
403617363	THIRD PARTY VERIFICATION
403617370	PRESSURE TEST
403624014	OFF-LOCATION FLOWLINE GIS SHP
403634579	ABANDONMENT IN PLACE DOCUMENTATION
403634703	PROPOSED ABANDONMENT LAYOUT DRAWING

Total Attach: 6 Files

### **General Comments**

**User Group**

**Comment**

**Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)