



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

OTHER

Comment: Unable to access location due to lock on gate

Corrective Action: Provide key, combinations, or alternate method of access to comply with rule 204.

Date: 07/30/2024

Overall Good:

**Spills:**

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 203449 Type: WELL API Number: 001-09008 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<p><a href="#">ECMC Inspection Report Summary</a>                      On 7/30/24 I, Inspector Justin Medina conducted an on-site inspection at:                      Well Name- Vetter 1-15A                      Company Name- Renegade                      API- 05-001-09008                      In Adams County Colorado.                      While there, I observed PR well                      During this inspection the following possible compliance issues were observed:                      Access. Rule 204. 7/30/24                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.                      This is a summary of inspection report.</p>	medinaj	07/30/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699506114	inspection pictures	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6645304">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6645304</a>