

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/30/2024

Submitted Date:

07/30/2024

Document Number:

699506117

**FIELD INSPECTION FORM**

Loc ID 320709 Inspector Name: MEDINA, JUSTIN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 41550  
Name of Operator: TYLER ROCKIES EXPLORATION LTD  
Address: P O BOX 119  
City: TYLER State: TX Zip: 75710-

**Findings:**

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Braden, David	303-969-9610	david@energyop.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
204603	WELL	SI	06/01/2023	OW	005-06688	AMOCO-UPRR-NOONEN-PRICE 1	SI

**General Comment:**

There have been no changes to equipment on location since previous inspection.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type OTHER

Comment: Stained soil in motor house needs to be removed

Corrective Action: Comply with rule 606.

Date: 08/30/2024

Overall Good:

**Spills:**

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 204603 Type: WELL API Number: 005-06688 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 12/30/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<p><a href="#">ECMC Inspection Report Summary</a>                      On 7/30/24 I, Inspector Justin Medina conducted an on-site inspection at:                      Well Name- AMOCO UPRR NOONED PRICE 1                      Company Name- TREX                      API- 05-005-06688                      In Arapahoe County Colorado.                      While there, I observed SI well                      During this inspection the following possible compliance issues were observed:                      Stained soil. Rule 606. 8/30/24                      A follow up on this site inspection needs to be conducted to ensure the compliance issues                      have been corrected to comply with ECMC rules.                      This is a summary of inspection report.</p>	medinaj	07/30/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699506118	inspection pictures	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6645306">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6645306</a>