

# Reclamation and Stormwater Inspection

Date: 07/23/2024

Operator: KERR MCGEE OIL & GAS ONSHORE LP -  
47120

Location ID: 306751

Inspection Document #: 708201430

Weld County, CO



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: Callen USX 65N 67W 27NWNE

Location ID: 306751



**Photo 1.** Entrance to the former tank battery has not been reclaimed, road base and culvert remain at the west (left photo) and east (right photo) entrances.



## Inspection Photos

Location Name: Callen USX 65N 67W 27NWE

Location ID: 306751



**Photo 2.** Three meter sheds and associated piping remain at the former tank battery location. The northern and southern meter sheds appear to be Kerr McGee gathering and the center meter shed appears to be PDC. All equipment must be removed and the location will need to be recontoured and reclaimed for future land use - cropland.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Number: 708201430

# Inspection Photos

Location Name: Callen USX 65N 67W 27NWNE

Location ID: 306751



**Photo 3.** Pipeline marker indicates Kerr Mcgee Gathering LLC.



Inspection Photos  
Location Name: Callen USX 65N 67W 27NWNE  
Location ID: 306751



**Photo 4.** Undesirable vegetation (kochia, russian thistle) observed around the meter sheds.

# Inspection Photos

Location Name: Callen USX 65N 67W 27NWNE

Location ID: 306751



**Photo 5.** Facing south along the former access road to well API 123-25194. Evidence of undesirable vegetation observed along the access road.



# Inspection Photos

Location Name: Callen USX 65N 67W 27NWNE

Location ID: 306751



**Photo 6.** Facing north at the former well location. Undesirable vegetation, predominantly kochia, observed throughout. Additional weed management/reclamation activities required.

# Inspection Photos

Location Name: Callen USX 65N 67W 27NWNE

Location ID: 306751



**Photo 7.** Facing east at the former well location; see comments in Photo 6.



# Inspection Photos

Location Name: Callen USX 65N 67W 27NWNE

Location ID: 306751



**Photo 8.** Facing south at the former well location; see comments in Photo 6.

# Inspection Photos

Location Name: Callen USX 65N 67W 27NWNE

Location ID: 306751



**Photo 9.** Facing west at the former well location; see comments in Photo 6.



# Inspection Photos

Location Name: Callen USX 65N 67W 27NWNE

Location ID: 306751



**Photo 10.** Reference area taken north of the former well location; crop has been recently harvested.