

Interim Reclamation and Stormwater Inspection

July 17, 2024

Operator: GMT EXPLORATION COMPANY LLC #10243

Location ID: 484163

Inspection Document #: 697505389

Elbert County, CO

Chris Binschus
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Cinnamon 6-64/19-7
Location ID: 484163



Photo 1. Photo taken from the entrance of location, illustrating the Operator sign.



Photo 2. Photo taken of wheat (left) and cereal rye (right). Cereal rye is an aggressive, undesirable annual grass that was observed throughout portions of the perimeter location and access road.



Inspection Photos
Location Name: Cinnamon 6-64/19-7
Location ID: 484163



Photo 3. Photo taken along a portion of the northern access road, facing Southwest. Photo illustrates and area alongside the access road that has been disturbed and seeded. Cereal rye is observed within this area.

Inspection Photos
Location Name: Cinnamon 6-64/19-7
Location ID: 484163



Photo 4. Photo taken from the eastern perimeter, facing Southwest. Photo illustrates the eastern and southern portions of location.



Photo 5. Photo taken from the eastern perimeter, facing West. Photo illustrates the majority of the working pad surface.

Inspection Photos
Location Name: Cinnamon 6-64/19-7
Location ID: 484163



Photo 6. Photo taken from the northeastern perimeter, facing West. Photo illustrates the northern perimeter which is mostly a cut slope that is in process of being stabilized with vegetation.



Photo 7. Photo taken from the eastern perimeter, facing South. Photo illustrates the eastern perimeter which is mostly a cut slope that is in process of being stabilized with vegetation.

Inspection Photos
Location Name: Cinnamon 6-64/19-7
Location ID: 484163



Photo 8. Photo taken from the southern perimeter, facing West. Photo illustrates the southern perimeter which is has a cut slope on the eastern half and fill slope on the western half.



Photo 9. Photo taken from the southwestern perimeter, facing Southwest. Photo illustrates the a topsoil stockpile and fill slope that have been seeded. Note- cereal rye was observed throughout portions of the southern perimeter.



Inspection Photos
Location Name: Cinnamon 6-64/19-7
Location ID: 484163



Photo 10. Photo taken from the southern perimeter, illustrating Cereal rye growth.



Photo 11. Photo taken from the western working pad surface, facing West. Photo illustrates a stabilized channel that is directed to a retention pond. The riprap was not lined underneath; therefore, stormwater erosion is undermining the riprap. CDPHE will be addressing this corrective action.



Inspection Photos
Location Name: Cinnamon 6-64/19-7
Location ID: 484163



Photo 12. Google Earth aerial imagery from 9/4/2023 illustrates the location and the northern portion of the access road.

