

# Interim Reclamation and Stormwater Inspection

July 17, 2024

Operator: GMT EXPLORATION COMPANY LLC #10243

Location ID: 478811

Inspection Document #: 697505391

Elbert County, CO

Chris Binschus  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Vulcan/6-64 10-8 Pad  
Location ID: 478811



**Photo 1.** Photo taken from the entrance of location off of the county road, illustrating the Operator sign.



**Photo 2.** Photo taken along a portion of the access road on the southern side, facing Southwest. Photo illustrates during the construction of the access road a buffered area was disturbed. A lot of this buffered area has established with vegetation but this photo illustrates an area that is predominantly annual vegetation and bare ground.



## Inspection Photos

Location Name: Vulcan/6-64 10-8 Pad

Location ID: 478811



**Photo 3.** Close up photo taken from the previous photo illustrating the predominantly annual vegetation and bare ground.



**Photo 4.** Reference area photo (right of the red-dashed line) illustrates the short-grass prairie vegetation dominated by blue grama and buffalo grass.



Inspection Photos  
Location Name: Vulcan/6-64 10-8 Pad  
Location ID: 478811



**Photo 5.** Photo taken along a portion of the northern access road, facing North. Photo illustrates during the construction of the access road a buffered area was disturbed. Photo illustrates an area that is predominantly annual vegetation and bare ground with some growth of introduced plant species, which is not reflective of reference area vegetation.

Inspection Photos  
Location Name: Vulcan/6-64 10-8 Pad  
Location ID: 478811



**Photo 6.** Photo taken along a portion of the northern interim reclamation area, facing North. Photo illustrates cereal rye was observed throughout interim reclamation areas.



## Inspection Photos

Location Name: Vulcan/6-64 10-8 Pad

Location ID: 478811




**Photo 7.** Photo taken from the northeastern interim reclamation, facing South. Photo illustrates a portion of the interim area that is established in wheatgrass likely from mulch with some desirable grass species within the understory.



**Photo 8.** Photo taken from the southern perimeter, facing West. See comments under Photo 7.



Inspection Photos  
Location Name: Vulcan/6-64 10-8 Pad  
Location ID: 478811



**Photo 9.** Google Earth aerial imagery from 9/4/2023 illustrates the location and the northern portion of the access road. Note- this imagery is prior to interim reclamation being completed.

