

## Inspection Photos

Location Name: CAERUS PICEANCE LLC CEDAR SPRINGS RANCH 2-14 (N2W) Pad

Location #: 324114



Photo # 3988 From entrance to location



Photo # 3989 Location

# Inspection Photos

Location Name: CAERUS PICEANCE LLC CEDAR SPRINGS RANCH 2-14 (N2W) Pad

Location #: 324114



Photo # 3990 Location



Photo # 3991 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC CEDAR SPRINGS RANCH 2-14 (N2W) Pad

Location #: 324114



Photo # 3992 Location



Photo # 3993 Stored supplies on location & in the interim area

## Inspection Photos

Location Name: CAERUS PICEANCE LLC CEDAR SPRINGS RANCH 2-14 (N2W) Pad

Location #: 324114



Photo # 3994 Stored supplies



Photo # 3995 Stored equipment & supplies on location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC CEDAR SPRINGS RANCH 2-14 (N2W) Pad

Location #: 324114




Photo # 3996 Wellhead sign has incorrect well # & API #