

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GENTRY E Pad

Location #: 335547



Photo # 3172 From entrance to location



Photo # 3173 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GENTRY E Pad

Location #: 335547



Photo # 3174 Location



Photo # 3175 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GENTRY E Pad

Location #: 335547



Photo # 3176 Location



Photo # 3177 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GENTRY E Pad

Location #: 335547



Photo # 3178 Open ended piping/available for entry by wildlife/wildlife hazard



Photo # 3179 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GENTRY E Pad

Location #: 335547



Photo # 3180 Debris



Photo # 3181 Wildlife egress on wellhead cellar not properly installed/needs adjustment

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GENTRY E Pad
Location #: 335547




Photo # 3182 Tank label contains inaccurate info/does not comply with CECMC rules

Photo # 3183 Tank label contains inaccurate info/does not comply with CECMC rules

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GENTRY E Pad

Location #: 335547



Photo # 3184 Tank label contains inaccurate info/does not comply with CECMC rules



Photo # 3185 Tank label contains inaccurate info/does not comply with CECMC rules



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GENTRY E Pad

Location #: 335547



Photo # 3186 Debris



Photo # 3187 Weeds/undesirable plant species on location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC GENTRY E Pad

Location #: 335547



Photo # 3188 Weeds/undesirable plant species on location



Photo # 3189 Weeds/undesirable plant species on location