

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/23/2024

Submitted Date:

07/24/2024

Document Number:

708201421**FIELD INSPECTION FORM**Loc ID 440776 Inspector Name: Edwardson, Dylan On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10459

Name of Operator: EXTRACTION OIL &amp; GAS INC

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

8 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		inspections@civiresources.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
440776	LOCATION	AC			-	Arellano 10-L Facility	RI
448614	TANK BATTERY	AC	12/08/2016		-	Arellano 10L Facility	RI

**General Comment:**

This is a Follow-up Interim Reclamation and Stormwater Inspection to the previous FIR (doc #708201213) conducted on 04/26/2024.

The Operator submitted FIRRs (doc #403819976 and doc #403859028) stating that the corrective actions have been completed.

**Location**Overall Good: ☐**Signs/Marker:**

Type	OTHER		
Comment:	Previous FIR (doc #708201213) documented that tank labels were faded, peeling and cracked. At the time of this inspection, it was observed that new signs/labels have been installed. Refer to attached inspection photos.		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:		
Corrective Action:		Date: _____

**Good Housekeeping:**

Type	OTHER		
Comment:	Previous FIR (doc #708201213) documented stained soil throughout equipment. The Operator submitted FIRR (doc #403819976) stating that the corrective action has been completed and stained soil has been cleaned and disposed. At the time of this inspection, it was not apparent that all stained soil previously documented appeared to have been disposed of. Additionally, new stained soil was observed within the tank battery (SW corner). Refer to attached inspection photos.		
Corrective Action:	Properly dispose of oily waste in accordance with Rule 905.e. Original CA date remains applicable.	Date:	05/24/2024
Type	UNUSED EQUIPMENT		
Comment:	Previous FIR (doc #708201213) documented unused equipment throughout the location. The Operator submitted FIRR (doc #403819976) stating that the corrective action has been completed and unused equipment has been removed from the location. At the time of this inspection, it was observed that some unused equipment was removed, however, previously document unused equipment remains. Refer to attached inspection photos.		
Corrective Action:	Comply with Rule 606. Original CA date remains applicable.	Date:	05/17/2024
Type	TRASH		
Comment:	Previous FIR (doc #708201213) documented trash and debris throughout the location. The Operator submitted FIRR (doc #403819976) stating that the corrective action has been completed and trash/debris has been removed from the location. At the time of this inspection, it appears that trash/debris has been removed.		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities									
Facility ID:	440776	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	448614	Type:	TANK	API Number:	-	Status:	AC	Insp. Status:	RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started:                      Date Interim Reclamation Completed:                     

Land Use: IMPROVED PASTURE

Comment:

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING                     

Comment

Corrective Action                      Date                     

1002b. SOIL REMOVAL AND  
SEGREGATION                     

Comment

Corrective Action                      Date                     

1002c. PROTECTION OF SOILS                     

Comment

Corrective Action                      Date                     

1002E. SURFACE DISTRURBANCE MINIMIZATION                     

Comment

Corrective Action                      Date                     

1003a. Waste and Debris removed?                     

Comment

Corrective Action                      Date                     

Unused or unneeded equipment onsite?                     

Comment

Corrective Action                      Date                     

Pit, cellars, rat holes and other bores closed?                     

Comment

Corrective Action                      Date                     

Guy line anchors marked?                     

Comment

Corrective Action                      Date

1003b. Area no longer in use? PassProduction areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-CroplandTop soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation In

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? P

Comment Previous FIR (doc #708201213) documented that the reclaimed portions were not progressing towards vegetative standards with undesirable vegetation observed. The Operator submitted FIR (doc #403819976) stating that the corrective action was complete and the location was reseeded and sprayed for undesirable vegetation. At the time of this inspection, it was observed that the interim areas appeared to have been seeded with evidence of drill rows and crimped mulch. This location will remain "in-process" until it can be inspected at a later date to verify vegetative compliance. Operator shall continue to monitor and manage this site until the location meets Rule 1003 standards, including stormwater and weed management.

Corrective Action

Date \_\_\_\_\_

Overall Interim Reclamation In Process**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_

Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: IMPROVED PASTURE

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_

Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_

No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_

Contoured \_\_\_\_\_

Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_

Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_

Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment:

Corrective Action:  Date

Overall Final Reclamation ☐ Well Release on Active Location ☐ Multi-Well Location ☐

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Comment:

Corrective Action:  Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403865050	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6638064">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6638064</a>
708201435	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6638056">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6638056</a>