

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403862228

Date Received:

07/23/2024

## FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 3 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-3779

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

ERIN JOSEPH

Phone

970-515-1169

Email

ECMCInspections@Oxy.com

### ECMC INSPECTION SUMMARY:

FIR Document Number: 714201280

Inspection Date: 07/12/2024

FIR Submit Date: 07/12/2024

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: KERR MCGEE OIL & GAS ONSHORE LP

Company Number: 47120

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-3779

### LOCATION - Location ID: 309856

Location Name: LUDWIG H-63N65W Number: 6SWNE County: \_\_\_\_\_

Qtrqtr: SWNE Sec: 6 Twp: 3N Range: 65W Meridian: 6

Latitude: 40.257954 Longitude: -104.705853

### FACILITY - API Number: 05-123- -00 Facility ID: 309856

Facility Name: LUDWIG H-63N65W Number: 6SWNE

Qtrqtr: SWNE Sec: 6 Twp: 3N Range: 65W Meridian: 6

Latitude: 40.257954 Longitude: -104.705853

### CORRECTIVE ACTIONS:

1 ☒ CA# 196762

Corrective Action: Comply with 603.o.

Date: 08/31/2024

Response: CA COMPLETED

Date of Completion: 07/16/2024

Operator Comment: This location is OOS and the vessel doesn't have fluid in it nor does it have any fluids running through it since it has been air gapped. Photos show the well head and separator air gapped per ECMC regulations. Aside from being air gapped, this location falls under the written spill contingency plan.

ECMC Decision: Approved pending re-inspection

ECMC Representative:			
3	✔	CA# 196764	
Corrective Action:	Comply with rule 603.o.		Date: 08/31/2024
Response:	CA COMPLETED		Date of Completion: 07/16/2024
Operator Comment:	This location is OOS and the vessel doesn't have fluid in it nor does it have any fluids running through it since it has been air gapped. Photos show the well head and separator air gapped per ECMC regulations. Aside from being air gapped, this location falls under the written spill contingency plan.		
ECMC Decision:	Approved pending re-inspection		
ECMC Representative:			

<u>OPERATOR COMMENT AND SUBMITTAL</u>	
Comment:	
I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.	
Print Name: ERIN JOSEPH	Signed: _____
Title: SR REGULATORY ADVISOR	Date: 7/23/2024 8:14:12 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403862228	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files