

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/26/2024

Submitted Date:

07/31/2024

Document Number:

716700006**FIELD INSPECTION FORM**Loc ID 313360 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: ☐**Operator Information:**

ECMC Operator Number: 10323

Name of Operator: ENTEK GRB LLC

Address: 165 SOUTH UNION #366

City: LAKEWOOD State: CO Zip: 80228

Status Summary:

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Neidel, Kris		kris.neidel@state.co.us	
Wilson, Justin	(970) 878-3825	jrwilson@blm.gov	
Roberts, James	970-620-6589	j75rober@blm.gov	
Andrews, Dave		david.andrews@state.co.us	
Murray, Richard		g.richard.murray@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
291259	WELL	SI	01/01/2014	GW	081-07395	BM FEDERAL 13-12 (OWP)	EI
485479	SPILL OR RELEASE	CL	02/22/2024		-	BM Federal #13-12 (OWP)	EI

General Comment:

On July 26, 2024 ECMC OWP staff members Richard Murray and Jim Hughes conducted a field inspection of the Entek BM Federal #13-12. For the most recent field inspection report of this facility, please refer to Document #704900136. This site visit was conducted to document current site conditions and secure the well head as much as possible from potential tampering.

Location				
Lease Road:				
Type	Access			
comment:	Dirt and gravel road behind stock panel gate with cattle guard.			
Corrective Action	L		Date:	
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Free standing sign near location entrance.			
Corrective Action:			Date:	
Emergency Contact Number:				
Comment:	<input type="text"/>			
Corrective Action:	<input type="text"/>			Date: <input type="text"/>
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:	<input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?				
Venting:				
Yes/No				
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities									
Facility ID:	291259	Type:	WELL	API Number:	081-07395	Status:	SI	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	485479	Type:	SPILL OR	API Number:	-	Status:	CL	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>On July 26, 2024 ECMC OWP staff members Richard Murray and Jim Hughes conducted a field inspection of the Entek BM Federal #13-12. For the most recent field inspection report of this facility, please refer to Document #704900136. This site visit was conducted to document current site conditions and secure the well head as much as possible from potential tampering.</p> <p>A 1" valve was observed to be leaking during this inspection. ECMC staff installed another 1" valve that stopped the leak.</p> <p>A 2" valve and plug have been installed, where a significant release of fluids had been occurring, since this location was last visited by ECMC staff.</p> <p>All of the valves on the BM Federal #13-12 were in the closed position at the conclusion of this field inspection.</p>	hughesjo	07/31/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716700007	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6646254