




Weeds, tear in 30-mil polyethylene canal liner.



Weeds/Animal tracks



WGS84
±16ft

40.04040, -104.85791

ft
±11ft

4955

° T
±12

NE24

**ECMC
Environmental
Field Inspection**



Facility 8 @ Sebold
© 17-Jul-24 02:00:47 PM
ECMC Environmental Inspection
Weeds/Debris/Trash



WGS84
±16ft

40.04039, -104.85789

ft
±10ft

4955


° T
±12

SW209

**ECMC
Environmental
Field Inspection**



Facility 8 @ Sebold
© 17-Jul-24 02:01:12 PM
ECMC Environmental Inspection
Weeds/Debris/Trash



Facility 8 @ Sebold
© 17-Jul-24 02:01:16 PM
ECMC Environmental Inspection
Weeds/Debris/Trash


**ECMC
Environmental
Field Inspection**



Facility 8 @ Sebold
© 17-Jul-24 02:01:25 PM
ECMC Environmental Inspection
Weeds/Debris/Trash

**ECMC
Environmental
Field Inspection**





Weeds. Excavation backfilled without ECMC review/approval.




Weeds/Debris/Trash. Footprint of work area



Facility 8 @ Sebold
© 17-Jul-24 02:02:17 PM
ECMC Environmental Inspection
Weeds. Footprint of work area.



Facility 8 @ Sebold
© 17-Jul-24 02:02:37 PM
ECMC Environmental Inspection
Weeds. Footprint of work area.




Weeds. Footprint of work area.



Weeds. Footprint of work area.


WGS84 ±16ft 40.04061, -104.85790 Δ ft ±11ft 4957 \triangle °,T ±12 NW294



Facility 8 @ Sebold
© 17-Jul-24 02:02:50 PM
ECMC Environmental Inspection


Weeds. Footprint of former work area (staging area/access/excavations/stockpiles).

WGS84 ±16ft 40.04061, -104.85791 Δ ft ±11ft 4958 \triangle °,T ±12 W257




Facility 8 @ Sebold
© 17-Jul-24 02:02:52 PM
ECMC Environmental Inspection


Weeds. Footprint of former work area (staging area/access/excavations/stockpiles).




Weeds/Debris/Trash. Footprint of work area/former stockpile. **Pieces of former E&P Waste Stockpile liner** and trash observed throughout work area.



Weeds/Debris/Trash. Footprint of work area/former stockpile. **Trash** observed in work area.




Weeds/Debris/Trash. Footprint of work area/former stockpile. Pieces of former E&P Waste Stockpile liner and trash observed throughout work area.




Weeds/Debris/Trash. Footprint of work area/former stockpile. Pieces of former E&P Waste Stockpile liner.




Weeds/Debris/Trash. Footprint of work area/former stockpile. Pieces of former E&P Waste Stockpile liner and trash observed throughout work area.




Weeds/Debris/Trash. Footprint of work area/former stockpile. Pieces of former E&P Waste Stockpile liner.




Weeds/Debris/Trash. Footprint of work area/former stockpile. Pieces of former E&P Waste Stockpile liner and trash observed throughout work area.




Weeds. Footprint of former work area (staging area/access/excavations/stockpiles).




Weeds/Debris/Trash. Footprint of work area/former stockpile. Pieces of former E&P Waste Stockpile liner and trash observed throughout work area.



Weeds/Debris/Trash. Pieces of former E&P Waste Stockpile liner and trash observed throughout work area.




Weeds. Footprint of former work area (staging area/access/excavations/stockpiles).



Weeds/debris/trash. Footprint of former work area (staging area/access/excavations/stockpiles).



Weeds. Footprint of former work area (staging area/access/excavations/stockpiles).



Weeds/debris/trash. Footprint of former work area (staging area/access/excavations/stockpiles).



Weeds/debris/trash. Footprint of former work area (staging area/access/excavations/stockpiles).