

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/08/2024

Submitted Date:

07/31/2024

Document Number:

699700388

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: Heil, John On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
3 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 ECMC Operator Number: 96850
 Name of Operator: TEP ROCKY MOUNTAIN LLC
 Address: 1058 COUNTY ROAD 215
 City: PARACHUTE State: CO Zip: 81635

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Cholas, Nick		nick.cholas@state.co.us	
,		COGCCInspectionReports@terraep.com	TEP

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
477727	PRODUCED WATER TRANSFER SYSTEM	CL	08/25/2020		-	PW_WestMammCreek	EI
487252	SPILL OR RELEASE	AC			-	TR 21-36-597 PW Transfer Line	EI

General Comment:
[ECMC Environmental Inspection.](#)

Inspected Facilities

Facility ID: 477727 Type: PRODUCED API Number: - Status: CL Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 487252 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Spills/Releases:

Type of Spill: PRODUCED WATER

Estimated Spill Volume: 100

Comment: See Initial Form 19 Doc #403845956 and Supplemental Form 19 Doc #403853321 for more information. ECMC staff John Heil and Nick Cholas conducted an Environmental Inspection of the spill/release area as well as the unknown tributary adjacent to Willow Creek. A detectable hydrocarbon odor was present around the spill/release area at time of inspection. A sheen was not present on the unknown tributary adjacent to Willow Creek as well as Willow Creek below the confluence of the two creeks.

Corrective Action: Operator shall comply with CAs on Mike Longworth Inspection 7/10/2024 Doc #701104046. Date: _____

Reportable: YES

GPS: Lat 39.576900

Long -108.224350

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Lat

Long

Field Parameters:

Sample Location: _____

Comment: _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699700389	20240708 Photo Log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6646799