

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	Area	Volume		corrective date
Type: Pump Jack		# 1		
Comment:				
Corrective Action:				Date:
Type: Prime Mover		# 1		
Comment:	Gas powered motor			
Corrective Action:				Date:
Type: Bradenhead		# 1		
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 204649 Type: WELL API Number: 005-06734 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: At time of inspection it appered flow line valves were in the closed position.

Corrective Action: Date:

BradenHead

Date of Last Brhd Test: 06/07/2024 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type:

End Surf Csg Pressure: 0

Comment:

Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
Routine inspecton	silverr	07/31/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707901561	loc pic	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6646803