

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 204815 Type: WELL API Number: 005-06900 Status: PR Insp. Status: PR

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well was down for rig work. Form 42 says MIRU for pump change. While on site I spoke with rig operator and he state they were testing tubing.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 09/06/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____ Date: _____

Corrective Action: _____ Date: _____

Workover

Comment: KPK rig 12 Form 42 MIRU on file with the ECMC

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
<u>Routine inspection.</u>	silverr	07/31/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707901563	loc pic	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6646804