

Work Completion Report

Contractor: Peerless

JOB DETAILS

Job Name	Month/Season	Completed By	Completion Date
RICE 6-3I7 TANK BATTERY	July	Armando Munoz	7/18/2024

Work Summary	Reclamation Type	Land Use
Repaired and stabilized erosion found on the NW corner of the tank containment and the NE corner of the flare backfilled and surfaced roughened. Installed rip rap chem dams.	Stormwater	Crop

One-Call Number	Red Zone Rep	Red Zone Date

WORK TASK

Task Name	Priority	COGCC Compliance	Task Location and Notes/Instructions
Stormwater Repairs	Normal	Yes	Location(s): RICE 6-3I7,O 6-6 JI FAC Notes: ECMC Corrective action due 8/9/2024. Please complete ASAP and send in completion report. Likely a lot of hand work due to some erosion being inside the chain link fence.

COMPLETION DETAILS

Total Area Affected: **10,546 sq ft**
Seed Mix: **None used**
Crop Type: **Corn**
Soil Type: **Clay Loam**
Stabilization Date: **7/18/2024**
Seeding Date:
Mulch: **None**
Straw Bales: **NA**
Soil Amendment Type: **None**
Soil Amendment Rate: **NA**
Imported Top Soil: **NA**
Top Soil Source: **NA**
General Notes:

PHOTOS

Photo Name: Site Map

Description:



Photo Name: Pre-Completion

Description:



Photo Name: Post-Completion

Description:



Photo Name: Rice2
Description:



Photo Name: Rice3

Description:



Photo Name: Rice4
Description:



Photo Name: Rice5

Description:



Photo Name: Rice6
Description:



Photo Name: Rice7

Description:

