

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/31/2024

Submitted Date:

07/31/2024

Document Number:

695110035

FIELD INSPECTION FORMLoc ID 308002 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10351

Name of Operator: WAPITI OPERATING LLC

Address: 1251 LUMPKIN RD

City: HOUSTON State: TX Zip: 77043

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
B Mattorano, Michael	575-445-6704/505-652-0416	mmattorano@wapitienergy.com	Production superintendent
B Berry, Matthew	575-445-6785/505-652-8275	mberry@wapitienergy.com	Production Foreman
B Middlebrook, Sonny	575-445-6724/575-445-8610	smiddlebrook@wapitienergy.com	All Inspections
B Madison, Randy	575-445-6706/575-420-1120	rmadison@wapitienergy.com	EHS Specialist

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
260123	WELL	PR	10/28/2001	CBM	071-07384	VPR C 63	PR

General Comment:

Location					
Overall Good: <input checked="" type="checkbox"/>					
Emergency Contact Number:					
Comment:				Date: _____	
Corrective Action:					
Overall Good: <input checked="" type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
Equipment:				corrective date	
Type: Gas Meter Run		# 1			
Comment:		CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.			
Corrective Action:					Date:
Type: Pump Jack		# 1			
Comment:					
Corrective Action:					Date:
Type: Deadman # & Marked		# 4			
Comment:					
Corrective Action:					Date:
Type: Bradenhead		# 1			
Comment:		IS ACCESSABLE			
Corrective Action:					Date:
Type: Ancillary equipment		# 1			
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No		NO			
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:				Date:	

Inspected Facilities									
Facility ID:	260123	Type:	WELL	API Number:	071-07384	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:				Date:					
BradenHead									
Date of Last Brhd Test:	10/23/2023		Annual Brhd Completed?	Yes					
Last Brhd Test Results	Initial Surf Csg Pressure:	0		Fluid Type:					
	End Surf Csg Pressure:	0							
Comment:									
Corrective Action:				Date:					

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695110036	INSP. PHOTOS	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6647149