

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/25/2024

Submitted Date:

07/25/2024

Document Number:

714201321**FIELD INSPECTION FORM**Loc ID 332679 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 10633Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLCAddress: 555 17TH STREET SUITE 3700City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**14 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
294001	WELL	PR	11/01/2023	OW	123-26671	BRANCH 4-6-23	PR

**General Comment:**[THIS IS A WELLHEAD/BATTERY INSPECTION.](#)

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Operator's name is no longer legible. See attached photos.		
Corrective Action:	Complyw ith Rule 605.	Date:	08/25/2024
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	WEEDS		
Comment:	overgrown vegetation inside tank battery berm. See attached photo.		
Corrective Action:	Comply with Rule 606.	Date:	08/08/2024
Type	UNUSED EQUIPMENT		
Comment:	Unused wellhead sign. See attached photos		
Corrective Action:	Comply with Rule 606	Date:	08/08/2024
Type	UNUSED EQUIPMENT		
Comment:	Unused/disconnected equipment (risers). See attached photos.		
Corrective Action:	Comply with Rule 609.c.	Date:	08/25/2024

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	panel		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	wire		
Corrective Action:		Date:	
Type	TANK BATTERY		

Comment: <a href="#">wire</a>			
Corrective Action:		Date:	

**Equipment:**

Type: Plunger Lift	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		,
Comment:					
Corrective Action:		Date:			

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity) 110 BBLS		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment: <a href="#">Shares containment with other tanks.</a>					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	OTHER	STEEL AST		,
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)	260 BBLS				
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date: <div></div>

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date: <div></div>

Flaring:

Type			
Comment:			
Corrective Action:			Date: <div></div>

Inspected Facilities									
Facility ID:	294001	Type:	WELL	API Number:	123-26671	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR; it appears the valves are in an open position.								
Corrective Action:				Date:					
BradenHead									
Date of Last Brhd Test:	02/27/2024		Annual Brhd Completed?	Yes					
Last Brhd Test Results	Initial Surf Csg Pressure:	16	Fluid Type:						
	End Surf Csg Pressure:	0							
Comment:									
Corrective Action:				Date:					

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				
Comment: <input type="text"/>						Date: <input type="text"/>
Corrective Action: <input type="text"/>						
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary</p> <p>WEATHER CONDITIONS: sunny, dry ground.</p> <p>On Thursday, July 25, 2024 at approximately 10:00, I, Inspector Brittani Santistevan, conducted an on-site inspection at BRANCH 4-6-23 (Crestone Peak Resources Operating, LLC), at location ID: 332679 in WELD COUNTY Colorado.</p> <p>While there, I observed a producing facility.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>1. Overgrown vegetation inside the tank battery berm. Comply with Rule 606. (Corrective Action Date: August 8, 2024) See attached photo #4.</p> <p>2. Unused/disconnected risers, not LOTO. Comply with Rule 609.c. (Corrective Action Date: August 25, 2024) See attached photo #6.</p> <p>3. Unused wellhead signage. Comply with Rule 606. (Corrective Action Date: August 8, 2024) See attached photo #7.</p> <p>4. It appears the operators name is no longer legible on the wellhead signage. Comply with Rule 605. (Corrective Action Date: August 25, 2024) See attached photo #8.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	santistb	07/25/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403865881	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6639019">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6639019</a>
714201322	Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6639016">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6639016</a>