

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/23/2024

Submitted Date:

07/25/2024

Document Number:

715500455

**FIELD INSPECTION FORM**

Loc ID 312848 Inspector Name: Burchett, Kirby On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10386  
Name of Operator: POC-I LLC  
Address: P.O. BOX 51208  
City: CASPER State: WY Zip: 82605

**Findings:**

- 9 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Neumiller, Wayne	(307) 237-7854	wayne@sunshinevalleypetroleum.com	
Podio, Rebecca	(307) 746-6468	rpodio@gmail.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222583	WELL	SI	02/01/2023	OW	081-05656	ILES DOME UNIT 24	SI

**General Comment:**

[CMC Inspection Report Summary](#)

On Tuesday, 07/23/2024, Inspector Kirby Burchett, performed a follow up inspection at POC-I LLC on the Iles Dome Unit 24 well, Location #312848, in Moffat County, Colorado.

This location is within or in close proximity to Parks and Wildlife (CPW) District with High Priority, NSO, Density, and Other Consultation Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

Follow up inspection in response to compliance issues observed during Insp. # 702501694 on 8/2/23. The following Corrective Actions issued during this inspection are unresolved and original due date will remain:

1. Debris.
2. Bradenheads not visible.
3. Well sign missing required information.

Refer to Inspection Photos for observed compliance issues.

While there during normal operations no additional compliance issues were observed.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Wellhead sign missing required information		
Corrective Action:	When no associated Tank battery is present at the Oil and Gas Location, the following information is required on the Well sign: Name of the Operator; Telephone number at which the Operator can be reached at all times; Telephone number for local emergency services (911 where available); The public road used to access the Well; Well name(s) and API number(s); The legal location of the Well(s) including the quarter/quarter section.	Date:	06/22/2023

**Emergency Contact Number:**

Comment:	307-237-7854	Date:	
Corrective Action:		Date:	

**Good Housekeeping:**

Type	DEBRIS		
Comment:	Random debris		
Corrective Action:	All trash, rubbish, and other waste material will be properly contained until removed from the Oil and Gas Location. At no time will trash, debris, or rubbish be placed or remain on the ground.	Date:	06/07/2023

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type			corrective date
Type: Submersible Pump	# 1		
Comment:	Fiberglass shed over wellhead		
Corrective Action:		Date:	
Type: Bradenhead	# 0		
Comment:	1 valve riser from cellar. Assume tubing/casing annulus. Well has surface, intermediate and production casing. No valves at surface to verify. Annual Bradenhead test report submitted 1/17/24.		
Corrective Action:	Install appropriate fittings to allow Bradenhead visual inspection.	Date:	06/02/2023
Type: Other	# 1		
Comment:	Enclosed shed with chemical tanks and equipment		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 5		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
--------	----	--	--

Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 222583 Type: WELL API Number: 081-05656 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: [Last Production - January 2023](#)  
[May 2024 Production Report](#)

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Operator is responsible for maintaining Best Management Practices \(BMPs\) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403865338	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6638521">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6638521</a>
715500456	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6638520">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6638520</a>