

Inspection Photos

07/31/2024

Operator: CHEVRON USA INC #16700

Location ID: 324350

Inspection Doc: 696206065

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CHEVRON USA INC #16700

Location ID: 324350



Photo 1: Photos 1-2 taken from the north end of the Location. Photos provide an overview of the Reclamation areas from east, southeast, southwest to west.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CHEVRON USA INC #16700

Location ID: 324350



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CHEVRON USA INC #16700

Location ID: 324350




Photo 3: Photo example showing areas of the Location that do not appear to be progressing towards 1004 Standards; areas of concern observed on both eastern and western areas of the reclaim. Thick accumulation of straw mulch evident within these areas, and appears to be hindering reclamation.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CHEVRON USA INC #16700

Location ID: 324350



Photo 4: Continued from photo 3. Photo example areas of the Location that do not appear to be progressing towards 1004 Standards



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CHEVRON USA INC #16700

Location ID: 324350



Photo 4: Continued from photo 3. Photo example areas on the west end of the Location that do not appear to be progressing towards 1004 Standards



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CHEVRON USA INC #16700

Location ID: 324350



Photo 6: Photo examples showing sections of erosion logs observed throughout the Location in disrepair.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CHEVRON USA INC #16700

Location ID: 324350



Photo 7: Photo examples showing silt fence observed throughout the Location in disrepair.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CHEVRON USA INC #16700

Location ID: 324350



Photo 8: Photo shows slope drain in disrepair.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CHEVRON USA INC #16700

Location ID: 324350



Photo 9: Photo example showing the vegetation within the adjacent reference area.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources