

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/31/2024

Submitted Date:

08/01/2024

Document Number:

694500696**FIELD INSPECTION FORM**Loc ID 316764 Inspector Name: NEIDEL, KRIS On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 6720Name of Operator: ROBERT L BAYLESS PRODUCER LLCAddress: 621 17TH ST STE 2300City: DENVER State: CO Zip: 80293**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Trujillo, Helen		htrujillo@rlbayless.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232726	WELL	SI	12/01/2023	OW	107-06140	DRY CREEK FEDERAL 1-14	EI

General Comment:

On 7/31/2024, ECMC staff; Kris Neidel inspected Dry Creek Federal 1-14, part of Remediation Project #19966. The following was observed: Well was SI at time of inspection, HRL compliance solutions was overseeing the removal of an unknown amount of contaminated soil from the former flare pit. Soil was being removed by a mini excavator and being hauled to Milner Landfill. At approximately 16 feet below ground surface, ground water was encountered. A sample of the water was collected for analysis of Table 915-1. Corrective Actions: Ensure all soils are compliant with Table 915-1. Groundwater shall be delineated for Table 915-1.

Inspected Facilities									
Facility ID:	232726	Type:	WELL	API Number:	107-06140	Status:	SI	Insp. Status:	EI
Producing Well									
Comment:									
Corrective Action:				Date:					

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental		
Spill/Remediation:		
Comment:	At approximately 16 feet below ground surface, ground water was encountered. A sample of the water was collected for analysis of Table 915-1	
Corrective Action:	Ensure all soils are compliant with Table 915-1. Groundwater shall be delineated for Table 915-1.	Date: 11/30/2024
Emission Control Burner (ECB): _____		
Comment:	_____	
Pilot: _____	Wildlife Protection Devices (fired vessels): _____	

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694500697	photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6648840