

FORM
6Rev
11/20

State of Colorado

Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

Replug By Other Operator

Document Number:

403874733

Date Received:

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

ECMC Operator Number: 10487

Contact Name: Deborah Abrams

Name of Operator: SPRINGDALE PARTNERS LLC

Phone: (303) 8942100

Address: 3409 MONTECLAIRE DR

Fax:

City: SHERMAN State: TX Zip: 75092

Email: deborah.abrams@state.co.us

For "Intent" 24 hour notice required,

Name: Schure, Kym

Tel: (970) 520-3832

ECMC contact:

Email: kym.schure@state.co.us

Type of Well Abandonment Report: ☒ Notice of Intent to Abandon ☐ Subsequent Report of Abandonment

API Number 05-075-09269-00

Well Name: SPRINGDALE UNIT BANEY

Well Number: 16-15 (OWP)

Location: QtrQtr: SWSE Section: 16 Township: 8N Range: 53W Meridian: 6

County: LOGAN

Federal, Indian or State Lease Number: 63/59

Field Name: SPRINGDALE

Field Number: 78300

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.654760

Longitude: -103.303700

GPS Data: GPS Quality Value: 2.2 Type of GPS Quality Value: Date of Measurement: 12/18/2013

Reason for Abandonment: ☐ Dry ☐ Production Sub-economic ☐ Mechanical Problems☒ Other OWPCasing to be pulled: ☐ Yes ☐ No Estimated Depth:Fish in Hole: ☒ Yes ☐ No If yes, explain details belowWellbore has Uncemented Casing leaks: ☐ Yes ☐ No If yes, explain details below

Details:

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
D SAND	4766	4770	09/17/2004	SQUEEZED	
J SAND	4861	4878			

Total: 2 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status
SURF	12+1/4	8+5/8	UNK	24	0	665	350	665	0	VISU
1ST	7+7/8	5+1/2	UNK	15.5	0	5003	235	5003	3800	CBL

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 4880 with 3 sacks cmt on top. CIBP #2: Depth 4691 with 3 sacks cmt on top.
CIBP #3: Depth 3921 with 3 sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 20 sks cmt from 715 ft. to 615 ft. Plug Type: ANNULUS Plug Tagged: ☐
Set 15 sks cmt from 715 ft. to 615 ft. Plug Type: CASING Plug Tagged: ☒
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Perforate and squeeze at 1440 ft. with 40 sacks. Leave at least 100 ft. in casing 1350 CICR Depth
Perforate and squeeze at 100 ft. with 35 sacks. Leave at least 100 ft. in casing _____ CICR Depth
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged: ☐

Set _____ sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☐ No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing Number of Days from Setting Surface Plug to Capping or Sealing the Well: _____
Surface Plug Setting Date: _____ Cut and Cap Date: _____

*Wireline Contractor: _____ *Cementing Contractor: _____

Type of Cement and Additives Used: _____

Flowline/Pipeline has been abandoned per Rule 1105 ☐ Yes ☐ No

Technical Detail/Comments:

CIBP @ 4880' (per doc #1131460). Verify top of CIBP before dumping 3 sks of cement on top.
Top of Fish @ 4893'

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Deborah Abrams
Title: OWP Date: _____ Email: deborah.abrams@state.co.us

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with ECMC Rules and applicable orders and is hereby approved.

ECMC Approved: _____ Date: _____

CONDITIONS OF APPROVAL, IF ANY LIST

Expiration Date: _____

COA Type **Description**

0 COA	

ATTACHMENT LIST

Att Doc Num

Name

403874766

WELLBORE DIAGRAM

Total Attach: 1 Files

General Comments

User Group

Comment

Comment Date

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)