

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/30/2024

Submitted Date:

08/01/2024

Document Number:

693807550**FIELD INSPECTION FORM**Loc ID 334170 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10453Name of Operator: PARADOX UPSTREAM LLCAddress: 500 DALLAS ST SUITE #1650City: HOUSTON State: TX Zip: 77002**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**14 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Hankins, Neil	970-428-2742	nhankins@americanhelium.us	All Inspections
Roberts, Jake		jroberts@americanhelium.us	All Inspections
Hartman, Laura		lhartman@blm.gov	
Demarco, Jaime		jdemarco@blm.gov	
Freese, Steve		steve.freese@state.co.us	
Gavito, Danielle	303-524-4651	dgavito@americanhelium.us	
Labowskie, Steve		steve.labowskie@state.co.us	
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277440	WELL	SI	07/01/2023	GW	113-06178	HC STATE 36-14-45-15	SI
278538	WELL	PR	10/01/2023	GW	113-06191	HC FED 31-11-45-14	SI
278541	WELL	SI	06/01/2023	GW	113-06188	HC FED 31-21-45-14	SI

General Comment:[ECMC staff performed a routine field inspection on 7/30/2024.](#)[Issues were found requiring corrective action. See inspection text and photos for details.](#)[Any Corrective Actions from previous inspections that have not been addressed are still applicable.](#)

Location				
Lease Road:				
Type	Main			
comment:				
Corrective Action	L			Date:
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Signs at wellheads illegible. Signs on meter housing. Sign on meter housing for HC FED #31-11-45-14 has wrong API#.			
Corrective Action:	Install sign to comply with Rule 605.g.			Date: 09/01/2024
Type	TANK LABELS/PLACARDS			
Comment:	Sign or label not posted or information inaccurate on tanks or containers or sign/label too small to read at distance or installed in place where not visible.			
Corrective Action:	Install sign to comply with Rule 605.h.			Date: 09/01/2024
Emergency Contact Number:				
Comment:	435-587-2237 Wrong Emergency contact number			
Corrective Action:	Install sign to comply with Rule 605.d.			Date: 09/01/2024
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment: <input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:	Panel fence			
Corrective Action:				Date:
Equipment:				
Type: Gas Meter Run	# 3			corrective date
Comment:	Gas meter calibration record not legible or conspicuously displayed at meter.			
Corrective Action:	Display legible meter calibration record in conspicuous location to comply with rule 430.d.(2).			Date: 08/11/2024
Type: Bradenhead	# 3			
Comment:				
Corrective Action:				Date:

Type: Bird Protectors	# 3		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 6		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	4	300 BBLS	STEEL AST		38.114354,-108.465702	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				
			Date:	

Venting:

Yes/No	YES		
Comment:	Enardo valve on tank battery venting. See Optical Gas Imaging section		
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			
		Date:	

Inspected Facilities

Facility ID: 277440 Type: WELL API Number: 113-06178 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Well shut in 6/2023. No MIT on record

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: 11/08/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 30 Fluid Type: VAPOR

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 278538 Type: WELL API Number: 113-06191 Status: PR Insp. Status: SI

Producing Well

Comment: Plunger lift. - Well not producing at time of inspection

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: 11/08/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 278541 Type: WELL API Number: 113-06188 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Well shut in 5/2023. No MIT on record.

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: 11/08/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

Optical Gas Imaging Survey

Survey Type: Routine

Current Operations: ☒ Production ☐ Workover ☐ Flowback ☐ Referred to APCD

GPS(entrance of location): Lat: Long:

Wind: Light Speed: 5 (mph) Direction From: W Weather: Partly Temperature: 90 (F)

Assisting Staff: Camera #:

☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM
-------------------	-------	-----------------	-------

Equipment Surveyed

Equipment
Separation Equipment
Wellhead(s)
Water Tank(s)

Comment:

Enardo valve on tank battery venting.

Corrective Action:

Inspect, maintain and repair tanks to comply with rule 609.b.

Date: 09/01/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693807551	Inspection photos 7/30/2024	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6649068