

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/30/2024

Submitted Date:

08/02/2024

Document Number:

693807552**FIELD INSPECTION FORM**Loc ID 334173 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10453Name of Operator: PARADOX UPSTREAM LLCAddress: 500 DALLAS ST SUITE #1650City: HOUSTON State: TX Zip: 77002**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**13 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Roberts, Jake		jroberts@americanhelium.us	All Inspections
Hankins, Neil	970-428-2742	nhankins@americanhelium.us	All Inspections
Demarco, Jaime		jdemarco@blm.gov	
Hartman, Laura		lhartman@blm.gov	
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Labowskie, Steve		steve.labowskie@state.co.us	
Gavito, Danielle	303-524-4651	dgavito@americanhelium.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282794	WELL	PR	01/01/2023	GW	113-06205	HC FED 31-31-45-14	SI
282801	WELL	PR	11/01/2019	GW	113-06206	HC FED 31-22-45-14	SI

General Comment:

ECMC staff performed a routine field inspection on 7/30/2024.
 Issues were found requiring corrective action. See inspection text and photos for details.
 Any Corrective Actions from previous inspections that have not been addressed are still applicable.

Location					
Lease Road:					
Type	Access				
comment:					
Corrective Action	L				Date:
Type	Main				
comment:					
Corrective Action	L				Date:
Overall Good: <input checked="" type="checkbox"/>					
Signs/Marker:					
Type	TANK LABELS/PLACARDS				
Comment:	Sign or label not posted or information inaccurate on tanks or containers or sign/label too small to read at distance or installed in place where not visible.				
Corrective Action:	Install sign to comply with Rule 605.h.				Date: 09/02/2024
Type	WELLHEAD				
Comment:	Signs at well not legible. Signs on Meter shed				
Corrective Action:	Corrective Action: Install sign to comply with Rule 605.g.				Date: 09/02/2024
Emergency Contact Number:					
Comment:	435-587-2237 Wrong Emergency contact number				
Corrective Action:	Install sign to comply with Rule 605.d				Date: 09/02/2024
Overall Good: <input checked="" type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment: <input type="text"/>					
<input type="checkbox"/> Multiple Spills and Releases?					
Fencing/:					
Type	WELLHEAD				
Comment:	Panel fence				
Corrective Action:					Date:
Equipment:					
				corrective date	
Type: Horizontal Heated Separator	# 2				
Comment:					
Corrective Action:					Date:
Type: Gas Meter Run	# 2				
Comment:	Gas meter calibration record not legible or conspicuously displayed at meter.				
Corrective Action:	Display legible meter calibration record in conspicuous location to comply with rule 430.d.(2).				Date: 08/12/2024
Type: Bird Protectors	# 2				
Comment:					

Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
OTHER	1	<50 BBLS	PLASTIC AST		,	
Comment:	Fresh water tank inside housing					
Corrective Action:					Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	300 BBLS	STEEL AST		38.112047,-108.460643	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities										
Facility ID:	282794	Type:	WELL	API Number:	113-06205	Status:	PR	Insp. Status:	SI	
Producing Well										
Comment:	Plunger lift - Not producing at time of inspection									
Corrective Action:								Date:		
BradenHead										
Date of Last Brhd Test:		11/08/2023		Annual Brhd Completed?		Yes				
Last Brhd Test Results		Initial Surf Csg Pressure:		24		Fluid Type: VAPOR				
		End Surf Csg Pressure:		0						
Comment:										
Corrective Action:									Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12										
Facility ID:	282801	Type:	WELL	API Number:	113-06206	Status:	PR	Insp. Status:	SI	
Producing Well										
Comment:	Plunger lift - Not producing at time of inspection									
Corrective Action:								Date:		
BradenHead										
Date of Last Brhd Test:		11/08/2023		Annual Brhd Completed?		Yes				
Last Brhd Test Results		Initial Surf Csg Pressure:		20		Fluid Type: VAPOR				
		End Surf Csg Pressure:		0						
Comment:										
Corrective Action:									Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12										

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

Optical Gas Imaging Survey

Survey Type: Routine

Current Operations: ☒ Production ☐ Workover ☐ Flowback ☐ Referred to APCD

GPS(entrance of location): Lat: Long:

Wind: Light Speed: 5 (mph) Direction From: W Weather: Partly Temperature: (F)

Assisting Staff: Camera #: 2

☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM	Equipment
				Separation Equipment
				Wellhead(s)
				Water Tank(s)

Comment: No FLIR detectable gas observed

Corrective Action: Date:

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693807553	Inspection photos 7/30/2024	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6649977