

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/30/2024

Submitted Date:

08/02/2024

Document Number:

693807564**FIELD INSPECTION FORM**Loc ID 316864 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: **Operator Information:**ECMC Operator Number: 10453Name of Operator: PARADOX UPSTREAM LLCAddress: 500 DALLAS ST SUITE #1650City: HOUSTON State: TX Zip: 77002**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**12 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|--------------|-----------------------------|-----------------|
| Browning, Chuck | 970-433-4139 | chuck.browning@state.co.us | Field Inspector |
| Labowskie, Steve | | steve.labowskie@state.co.us | |
| Hartman, Laura | | lhartman@blm.gov | |
| Demarco, Jaime | | jdemarco@blm.gov | |
| Hankins, Neil | 970-428-2742 | nhankins@americanhelium.us | All Inspections |
| Gavito, Danielle | 303-524-4651 | dgavito@americanhelium.us | |
| Roberts, Jake | | jroberts@americanhelium.us | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 285042 | WELL | PR | 09/01/2020 | GW | 113-06217 | HC FED 25-44-45-15 | PR |

General Comment:

ECMC staff performed a routine field inspection on 7/30/2024.
 Issues were found requiring corrective action. See inspection text and photos for details.
 Any Corrective Actions from previous inspections that have not been addressed are still applicable.

| Location | | | | |
|--|--|--------|-------|------------------|
| Lease Road: | | | | |
| Type | Main | | | |
| comment: | | | | |
| Corrective Action | L | | Date: | |
| Type | Access | | | |
| comment: | | | | |
| Corrective Action | L | | Date: | |
| Overall Good: <input checked="" type="checkbox"/> | | | | |
| Signs/Marker: | | | | |
| Type | TANK LABELS/PLACARDS | | | |
| Comment: | Sign or label not posted or information inaccurate on tanks or containers or sign/label too small to read at distance or installed in place where not visible. | | | |
| Corrective Action: | Install sign to comply with Rule 605.h. | | | Date: 09/14/2024 |
| Type | WELLHEAD | | | |
| Comment: | Sign on meter housing | | | |
| Corrective Action: | | | | Date: |
| Emergency Contact Number: | | | | |
| Comment: | 435-587-2237 Wrong Emergency contact number | | | |
| Corrective Action: | Install sign to comply with Rule 605.d. | | | Date: 09/08/2024 |
| Overall Good: <input checked="" type="checkbox"/> | | | | |
| Spills: | | | | |
| Type | Area | Volume | | |
| In Containment: No | | | | |
| Comment: | | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |
| Fencing/: | | | | |
| Type | WELLHEAD | | | |
| Comment: | Panel fence | | | |
| Corrective Action: | | | | Date: |
| Equipment: | | | | |
| Type: Bradenhead | # 1 | | | corrective date |
| Comment: | | | | |
| Corrective Action: | | | | Date: |
| Type: Gas Meter Run | # 1 | | | |
| Comment: | Gas meter calibration record not legible or conspicuously displayed at meter. | | | |
| Corrective Action: | Display legible meter calibration record in conspicuous location to comply with rule 430.d.(2). | | | Date: 08/13/2024 |
| Type: Bird Protectors | # 1 | | | |

| | | | |
|-----------------------------------|-----|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Deadman # & Marked | # 4 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| | | | | | | |
|--------------------|--|----------|-----------|---------|-----------------------|------------------|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| PRODUCED WATER | 1 | 300 BBLs | STEEL AST | | 38.118781,-108.465479 | |
| Comment: | Tank rusted out. Tanks are rusted , pitted, or peeling paint, or show evidence of inadequate repair. | | | | | |
| Corrective Action: | Inspect, maintain and repair tanks to comply with rule 609.b. | | | | | Date: 09/02/2024 |

Paint

| | |
|------------------|--|
| Condition | |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | |
| | | Date: | | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | | | | | | | |
|-------------------------|--|-------|------------------------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 285042 | Type: | WELL | API Number: | 113-06217 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Plunger lift- Not producing at time of inspection. | | | | | | | | |
| Corrective Action: | | | | Date: | | | | | |
| BradenHead | | | | | | | | | |
| Date of Last Brhd Test: | 11/09/2023 | | Annual Brhd Completed? | Yes | | | | | |
| Last Brhd Test Results | Initial Surf Csg Pressure: | 0 | | Fluid Type: | NONE | | | | |
| | End Surf Csg Pressure: | 0 | | | | | | | |
| Comment: | | | | | | | | | |
| Corrective Action: | | | | Date: | | | | | |

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | | | |

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

Optical Gas Imaging SurveySurvey Type: RoutineCurrent Operations: ☒ Production ☐ Workover ☐ Flowback ☐ Referred to APCD

GPS(entrance of location): Lat: _____ Long: _____

Wind: Light Speed: 5 (mph) Direction From: W Weather: Partly Temperature: 95 (F)Assisting Staff: _____ Camera #: 2☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

| Time Survey Start | AM/PM | Time Survey End | AM/PM |
|-------------------|-------|-----------------|-------|
|-------------------|-------|-----------------|-------|

| |
|----------------------|
| Equipment |
| Water Tank(s) |
| Wellhead(s) |
| Separation Equipment |

Comment: No FLIR detectable gas observedCorrective
Action:

Date:

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--------------------------------|---|
| 693807565 | Inspection photos 7/30/2024 | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6650241 |