

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
07/31/2024
Submitted Date:
08/03/2024
Document Number:
708904284

FIELD INSPECTION FORM

Loc ID 311599 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

6 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
456914	Domestic Tap	AC	08/28/2018		-	Domestic Tap RWF 342-33	AC

General Comment:

[CECMC Inspection Report Summary](#)
On 07/31/2024 at approximately 11:46 hours, I, Compliance Specialist, Wayne Smelser Conducted a domestic tap inspection at TEP ROCKY MOUNTAIN LLC Domestic Tap RWF 342-33 Location # 311599 in Garfield County Colorado.
While there, I observed the domestic tap is derived from TEP sales line.

[This is a summary of inspection report](#)

Location				
Lease Road:				
	Type Access			
	comment:			
	Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>				
Emergency Contact Number:				
	Comment:	<input style="width: 80%;" type="text"/>		
	Corrective Action:	<input style="width: 80%;" type="text"/>		
Date: _____				
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
	Comment:	<input style="width: 80%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
	Type OTHER			
	Comment: Domestic tap - pipe rail fence			
	Corrective Action:			Date:
Equipment:				
				corrective date
Type: Other		# 1		
	Comment: Domestic tap			
	Corrective Action:			Date:
Venting:				
	Yes/No NO			
	Comment:			
	Corrective Action:			Date:
Flaring:				
Type				
	Comment:			
	Corrective Action:			Date:

Inspected Facilities

Facility ID: 456914 Type: Domestic Tap API Number: - Status: AC Insp. Status: AC

Producing Well

Comment: While there, I observed the domestic tap is derived from TEP sales line. The pressure is regulated by a big Joe regulator. Following the regulator there is a fluid knock out with a PRV on it followed by a little joe regulator & then an in line odorizer. All fittings appear to be adequately sized.

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date:

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Domestic tap inspection only	smelserw	08/03/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708904285	Inspection 708904284 photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6650685