

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/31/2024

Submitted Date:

08/04/2024

Document Number:

708904292**FIELD INSPECTION FORM**Loc ID 323996 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: 1058 COUNTY ROAD 215City: PARACHUTE State: CO Zip: 81635**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**22 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211442	WELL	PR	06/14/1998	GW	045-07202	QUARTER CIRCLE RANCH RMV 104-33	PR
426327	TANK BATTERY	AC	04/14/2009		-	QUARTER CIRCLE RANCH-66S94W 33NENE	AC

General Comment:**CECMC Inspection Report Summary**

On 07/31/2024 at approximately 11:29 hours, I, Compliance Specialist, Wayne Smelser

Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC QUARTER CIRCLE RANCH RMV 104-33 Pad.

Location # 323996 in Garfield County Colorado.

Location is within High Priority/Density/NSO/Black Bear Habitat areas & Bald Eagle Roost site.

Location is approximately 21 yards from the Colorado River.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Equipment - Open ended piping on separator unit/wildlife hazard with a CA date of 08/11/2024

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator unit includes attached storage tank. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical tank		
Corrective Action:		Date:	

Emergency Contact Number:		
Comment:	911/970-285-9377	
Corrective Action:		Date: _____

Overall Good: ☐

Spills:				
Type	Area	Volume		
In Containment:	No			
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:			
Type	OTHER		
Comment:	Chemical tank - hog panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	

Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:	Well on plunger lift		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Taylor plug located on bradenhead, bradenhead valve accessible.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 1		
Comment:	Marked		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical tank		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Open ended piping on separator unit/available for entry by wildlife/wildlife hazard		
Corrective Action:	Comply with CECMC wildlife rules	Date:	08/11/2024
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLS	STEEL AST		,	
Comment:	Tank equipped with telemetry					
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		

Other (Capacity) 80 bbl						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)		Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient				
Comment: Centralized containment						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	200 BBLS	STEEL AST		,	
Comment: Tank equipped with telemetry						
Corrective Action:						Date:
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)		Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient				
Comment: Centralized containment						
Corrective Action:						Date:
<u>Venting:</u>						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
<u>Flaring:</u>						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities				
Facility ID: 211442	Type: WELL	API Number: 045-07202	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing, well on plunger lift			
Corrective Action:				Date:
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 426327	Type: TANK	API Number: -	Status: AC	Insp. Status: AC
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				Sparse to none in sections
		Rip Rap				
Sediment Traps						
Rip Rap						
Ditches						
Check Dams						
		Culverts				
Berms						
		Ditches				
Compaction						Light compaction in some areas
Gravel						Sparse to none in areas
		Compaction				

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Please refer to Equipment for corrective action	smelserw	08/04/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708904293	Inspection 708904292 photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6651081
708904294	Inspection 708904292 Stormwater photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6651082