

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/23/2024

Submitted Date:

07/29/2024

Document Number:

693807521

**FIELD INSPECTION FORM**

Loc ID 316861 Inspector Name: BROWNING, CHUCK On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10453  
Name of Operator: PARADOX UPSTREAM LLC  
Address: 500 DALLAS ST SUITE #1650  
City: HOUSTON State: TX Zip: 77002

**Findings:**

- 11 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Gavito, Danielle	303-524-4651	dgavito@americanhelium.us	
Roberts, Jake		jroberts@americanhelium.us	All Inspections
Hankins, Neil	970-428-2742	nhankins@americanhelium.us	All Inspections
Labowskie, Steve		steve.labowskie@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
283802	WELL	TA	11/01/2023	GW	113-06211	HC STATE 36-34B-45-15	TA

**General Comment:**

ECMC staff performed a routine field inspection on 7/23/2024.  
Issues were found requiring corrective action. See inspection text and photos for details.  
Any Corrective Actions from previous inspections that have not been addressed are still applicable.

Location			
<b>Lease Road:</b>			
	Type Access		
	comment:		
	Corrective ActionL		Date:
	Type Main		
	comment:		
	Corrective ActionL		Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
	Type TANK LABELS/PLACARDS		
	Comment: Sign or label not posted or information inaccurate on tanks or containers or sign/label too small to read at distance or installed in place where not visible.		
	Corrective Action: Install sign to comply with Rule 605.h.		Date: 08/24/2024
	Type WELLHEAD		
	Comment: Sign not legible Sign not updated to reflect current operator		
	Corrective Action: Install sign to comply with Rule 605.g.		Date: 08/30/2024
Emergency Contact Number:			
	Comment: 435-587-2237 Wrong Emergency contact number		
	Corrective Action: Install sign to comply with Rule 605.d.		Date: 08/30/2024
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
	Comment: <input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
	Type WELLHEAD		
	Comment: Panel fence		
	Corrective Action:		Date:
	Type SEPARATOR		
	Comment: Pipe barricade		
	Corrective Action:		Date:
<b>Equipment:</b>			
Type: Gas Meter Run	# 1		corrective date
	Comment: Gas meter calibration record not legible or conspicuously displayed at meter.		
	Corrective Action: Display legible meter calibration record in conspicuous location to comply with rule 430.d.(2).		Date: 08/10/2024
Type: Plunger Lift	# 1		

Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLs	STEEL AST		38.107664,-108.465965
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 283802 Type: WELL API Number: 113-06211 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Well shut in 3/1/2021.  
Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to Plug Well.

Corrective Action: Produce well after performing successful mechanical integrity test per Rule 417 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.

Date: 08/30/2024

**BradenHead**

Date of Last Brhd Test: 11/06/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 10 Fluid Type: VAPOR

End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403868983	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6642791">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6642791</a>
693807522	Inspection photos 7/23/2024	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6642771">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6642771</a>