

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/23/2024

Submitted Date:

07/29/2024

Document Number:

693807535

**FIELD INSPECTION FORM**

Loc ID 333120 Inspector Name: BROWNING, CHUCK On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10453  
Name of Operator: PARADOX UPSTREAM LLC  
Address: 500 DALLAS ST SUITE #1650  
City: HOUSTON State: TX Zip: 77002

**Findings:**

- 11 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Hankins, Neil	970-428-2742	nhankins@americanhelium.us	<a href="#">All Inspections</a>
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	<a href="#">Field Inspector</a>
Roberts, Jake		jroberts@americanhelium.us	<a href="#">All Inspections</a>
Gavito, Danielle	303-524-4651	dgavito@americanhelium.us	
Labowskie, Steve		steve.labowskie@state.co.us	
Freese, Steve		steve.freese@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232858	WELL	SI	10/01/2023	GW	113-06047	STATE 1-36H	SI

**General Comment:**

ECMC staff performed a routine field inspection on 7/23/2024.  
Issues were found requiring corrective action. See inspection text and photos for details.  
Any Corrective Actions from previous inspections that have not been addressed are still applicable.

Location			
<b>Lease Road:</b>			
Type	Main		
comment:			
Corrective ActionL		Date:	
Type	Access		
comment:			
Corrective ActionL		Date:	
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Sign or label not posted or information inaccurate on tanks or containers or sign/label too small to read at distance or installed in place where not visible.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	08/30/2024
Type	WELLHEAD		
Comment:			
Corrective Action:			
Emergency Contact Number:			
Comment:	435-587-2237 Wrong Emergency contact number		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	08/30/2024
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Panel fence		
Corrective Action:			
		Date:	
<b>Equipment:</b>			
Type:	Horizontal Heated Separator	# 1	corrective date
Comment:			
Corrective Action:			
Date:			
Type:	Deadman # & Marked	# 4	
Comment:			
Corrective Action:			
Date:			
Type:	Bird Protectors	# 1	
Comment:			
Corrective Action:			
Date:			

Type: Gas Meter Run	# 1	
Comment:	Gas meter calibration record not legible or conspicuously displayed at meter.	
Corrective Action:	Display legible meter calibration record in conspicuous location to comply with rule 430.d.(2).	Date: 08/10/2024
Type: Plunger Lift	# 1	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLs	STEEL AST		38.111038,-108.475274
Comment:	Tanks are rusted , pitted, or peeling paint, or show evidence of inadequate repair.				
Corrective Action:	Inspect, maintain and repair tanks to comply with rule 609.b.				Date: 08/30/2024

**Paint**

Condition	Inadequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 232858 Type: WELL API Number: 113-06047 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Well shut in 9/1/2023.  
Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to Plug Well.

Corrective Action: Produce well after performing successful mechanical integrity test per Rule 417 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.

Date: 08/30/2024

**BradenHead**

Date of Last Brhd Test: 11/07/2023 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

### Optical Gas Imaging Survey

Survey Type: Routine

Current Operations:    Production    Workover    Flowback    Referred to APCD

GPS(entrance of location): Lat: 38.111662                      Long: -108.474038

Wind: Light    Speed: 5 (mph)    Direction From: W    Weather: Clear    Temperature: 90 (F)

Assisting Staff: \_\_\_\_\_                      Camera #: 2

Visible Smoke                       Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM
11:35	AM	11:36	AM

Equipment
Water Tank(s)
Separation Equipment
Wellhead(s)

Comment: No FLIR detectable gas observed

Corrective Action:

Date:

#### Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403869523	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6643170">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6643170</a>
693807536	Inspection photos 7/23/2024	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6643160">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6643160</a>