

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/11/2024

Submitted Date:

07/29/2024

Document Number:

711901042**FIELD INSPECTION FORM**Loc ID 316973 Inspector Name: SCHURE, KYM On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10690Name of Operator: IMPETRO RESOURCES LLCAddress: 558 CASTLE PINES PKWY UNIT B-4City: CASTLE PINES State: CO Zip: 80108**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|----------------|--------------|-------------------------------|---------------------------------|
| Bongers, Brent | 361-935-5633 | bbongers@impetroresources.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|
| 233649 | WELL | PR | 09/01/2017 | OW | 121-05709 | MARICK STATE 1 | PR |

General Comment:[ROUTINE FIR](#) - CA'S CITED WITHIN THIS FIR -

Location**Lease Road:**

| | | | |
|-------------------|----------------------|-------|--|
| Type | Access | | |
| comment: | MAINTAIN LEASE ROADS | | |
| Corrective Action | L | Date: | |

Overall Good: ☐**Signs/Marker:**

| | | | |
|--------------------|--------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | SATISFACTORY | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | | |
|--------------------|--------------|-------|--|
| Comment: | SATISFACTORY | | |
| Corrective Action: | | Date: | |

Overall Good: ☐**Spills:**

| | | | | |
|--------------------|---|--------|--|------------------|
| Type | Area | Volume | | |
| Crude Oil | WELLHEAD | | | |
| Comment: | REPAIR LEAK AT WELLHEAD - REMOVE AND REMEDIATE AFFECTED SOILS NON - REPORTABLE. UNLESS SPILL HAS INCREASED SINCE FIR SUBMITTED | | | |
| Corrective Action: | COMPLY WITH RULE 912 SERIES - COMPLY WITH RULE 912.a (24) HRS. TO REMOVE FREE FLUIDS - (3) DAYS TO CLEAN UP SOILS | | | Date: 07/30/2024 |

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

| | | | |
|--------------------|-----------|-------|-----------------|
| Type: Other | # 0 | | corrective date |
| Comment: | NO CHANGE | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | | | | | | | |
|----------------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 233649 | Type: | WELL | API Number: | 121-05709 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | OW | | | | | | | | |
| Corrective Action: | | | | Date: | | | | | |

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 403869847 | INSPECTION SUBMITTED | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6643587 |
| 711901068 | SPILL PHOTOS | https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6643585 |