

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/05/2024

Submitted Date:

08/05/2024

Document Number:

715800059

FIELD INSPECTION FORMLoc ID 421518 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		ECMCInspections@Oxy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
425963	TANK BATTERY	AC	02/08/2011		-	BADDING TANK BATTERY 20-26SX	AC

General Comment:

This is an AML.

Inspected Facilities				
Facility ID: 425963	Type: TANK	API Number: -	Status: AC	Insp. Status: AC
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
ECMC Comments				
Comment	User	Date		
Follow up inspection to Doc# 702403404 in response to FIRR #403863271. Based on photos submitted by the operator corrective actions are complete. (Photos attached to FIRR)	revasr	08/05/2024		