

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/01/2024

Submitted Date:

08/05/2024

Document Number:

708904309

**FIELD INSPECTION FORM**Loc ID 335216 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

27 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211554	WELL	PR	11/10/1998	GW	045-07314	SAVAGE RMV #111-33	PR
259292	WELL	PR	02/14/2001	GW	045-07708	SAVAGE RWF 322-33	PR
259333	WELL	PR	02/19/2001	GW	045-07715	SAVAGE RWF 332-33	PR
259335	WELL	PR	01/26/2001	GW	045-07717	SAVAGE RWF 321-33	PR

**General Comment:****CECMC Inspection Report Summary**

On 08/01/2024 at approximately 11:55 hours, I, Compliance Specialist, Wayne Smelser  
Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC SAVAGE RMV111-33 Pad.  
Location # 335216 in Garfield County Colorado.  
Location is within High Priority/Density/Black Bear Habitat areas.  
While there, I observed normal production operations.

This is a summary of inspection report.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Sign weathered & cracking but still legible at this time		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical tank		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Signs weathered & cracking but still legible at this time		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-9377

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	OTHER		
Comment:	Methanol tank - hog panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	

Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Chemical tank & flameless gas infrared catalytic heater - hog panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	

**Equipment:**

			corrective date
Type: Plunger Lift	# 4		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Gas Meter Run	# 4		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Flameless gas infrared catalytic heater		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 9		
Comment:	Marked		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical tank		
Corrective Action:		Date:	
Type: Bradenhead	# 4		
Comment:	Taylor plugs located on all bradenhead, bradenhead valves are accessible.		
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	200 BBLS	STEEL AST		,	
Comment:	Tank equipped with telemetry					
Corrective Action:					Date:	

**Paint**

Inspector Name: Smelser, Wayne

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate				
Comment:	Separate containment				
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
METHANOL	1	<50 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	500 gal	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient			
Comment:	Separate containment				
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities			
Facility ID: 211554	Type: WELL	API Number: 045-07314	Status: PR      Insp. Status: PR
Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID: 259292	Type: WELL	API Number: 045-07708	Status: PR      Insp. Status: PR
Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID: 259333	Type: WELL	API Number: 045-07715	Status: PR      Insp. Status: PR
Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID: 259335	Type: WELL	API Number: 045-07717	Status: PR      Insp. Status: PR
Producing Well			
Comment:	Producing, well on plunger lift		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						Sparse to none in most areas
		Culverts				
		Compaction				
		Ditches				
		Gravel				Sparse to none in sections
				Material Handling And Spill Prevention		Chemical tank containment
Compaction						Light compaction in some areas

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708904310	Inspection 708904309 photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6652849">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6652849</a>
708904311	Inspection 708904309 Stormwater photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6652850">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6652850</a>