

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/24/2024

Submitted Date:

08/06/2024

Document Number:

717000026

**FIELD INSPECTION FORM**

Loc ID 475504 Inspector Name: Finkenbinder, Chane On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10695  
Name of Operator: BEHRENS RESOURCES INC  
Address: PO BOX 188  
City: DEER TRAIL State: CO Zip: 80135

**Findings:**

5 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		michael.hickey@state.co.us	

**General Comment:**

[Routine OWP inspection](#)

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

Comment: Weeds throughout

Corrective Action:

Date:

Overall Good:

**Spills:**

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

corrective date

Type: Emission Control Device

# 1

Comment: Bird screening in ECD has fallen in the unit and there are multiple dead raptors ( 3 Kestrels & 3 barn owls ) and 1 living barn owl. the one living barn owl appeared to leave that following night.

Corrective Action:

Date:

Type: Vertical Heated Separator

# 1

Comment:

Corrective Action:

Date:

Type: Bird Protectors

# 2

Comment: Bird screening in ECD has fallen in the unit and there are multiple dead raptors ( 3 Kestrels & 3 barn owls ) and 1 living barn owl. the one living barn owl appeared to leave that following night.

Corrective Action:

Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		39.833498,-104.536469

Comment:

Corrective Action:

Date:

**Paint**

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	Open Top		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Wells Served By Facilities Above**

**AirsID**

API Number	API Number	AirsID
001-07466		

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**ECMC Comments**

Comment	User	Date
Bird screening in ECD has fallen in the unit and there are multiple dead raptors ( 3 Kestrels & 3 barn owls ) and 1 living barn owl. the one living barn owl appeared to leave that following night.	finkenbc	08/06/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717000030	Inspection photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6653129">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6653129</a>
717000031	video	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6653130">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6653130</a>