

Inspection Photos
Location Name: Focus Ranch Unit Federal #12-1
API: 05-107-06221



Adjacent hillside has slumped and made access road impassable.



Access road is impassable where slump occurred.

Inspection Photos
Location Name: Focus Ranch Unit Federal #12-1
API: 05-107-06221



Approximately 1.5 miles from the location the access road has become impassable.

Access road bisected by hillside slump.