

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/31/2024

Submitted Date:

08/06/2024

Document Number:

697505418**FIELD INSPECTION FORM**Loc ID 330572 Inspector Name: Binschus, Chris On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1099 18TH STREET SUITE 1500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|---|---------------------------------|
| , | | rbucogccinspectionreports@c hevron.onmicrosoft.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 251500 | WELL | PA | 04/08/2021 | GW | 123-19303 | BIHAIN 26-4 | RI |

General Comment:

This is a desktop final reclamation inspection in response to a Form 4 Final Reclamation Complete Notice (Doc. # 403853399) using cropland drone documentation per the ECMC Operator Guidance.

This is a Final Reclamation Inspection for PA Well AP#123-19303. Well was plugged and abandoned 04/08/2021.

Location

Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good: ☐

Spills:

| Type | Area | Volume | | |
|--|------|--------|--|--|
| In Containment: No | | | | |
| Comment: | | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |

Equipment:

| Type: | # | | corrective date |
|--------------------|---|--|-----------------|
| Comment: | Based on Operator supplied information, all equipment has been removed from the location. | | |
| Corrective Action: | | | Date: |

Venting:

| | | |
|--------------------|--|-------|
| Yes/No | | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

| Inspected Facilities | | | | | | | | | |
|--|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 251500 | Type: | WELL | API Number: | 123-19303 | Status: | PA | Insp. Status: | RI |
| The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12 | | | | | | | | | |

| Environmental | | | |
|-----------------------------------|--|-------------------------------|----------------------|
| Spills/Releases: | | | |
| Type of Spill: _____ | | Estimated Spill Volume: _____ | |
| Comment: | <div>After reviewing the Operator supplied information, ECMC confirms that all Spill and Remediation projects are approved and closed.</div> | | |
| Corrective Action: | <div></div> | | Date: _____ |
| Reportable: _____ | GPS: Lat _____ | Long _____ | |
| Proximity to Surface Water: _____ | Depth to Ground Water: _____ | | |
| Water Well Complaint: | | | |
| DWR Receipt Num: _____ | Owner Name: _____ | GPS : _____ | Lat _____ Long _____ |
| Field Parameters: | | | |
| <div></div> | | | |
| Sample Location: _____ | | Comment: _____ | |

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____ Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____ Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____ Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____ Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____ Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____ Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____ Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____ Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment _____

Corrective Action _____ Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged Pass Pit mouse/rat holes, cellars backfilled Pass

Debris removed Pass No disturbance /Location never built _____

Access Roads Regraded Pass Contoured Pass Culverts removed _____

Gravel removed Pass

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage Pass

Weeds present Pass Subsidence Pass

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment:

| | | |
|---|-------------|---|
| <p>After reviewing the Operator supplied drone imagery, the Operator removed gravel, regraded and contoured the disturbance areas. More than two growing seasons have indicated no significant unrestored subsidence. The well location and access road are reflective of reference crop areas and meet Rule 1004 standards.</p> <p>The associated tank battery will be addressed with a separate field inspection report under Location ID 472160 once a Final Reclamation Complete Notice has been submitted.</p> | | |
| Corrective Action: | <div></div> | Date <div></div> |
| Overall Final Reclamation | Pass | Well Release on Active Location <input type="checkbox"/> Multi-Well Location <input type="checkbox"/> |

Storm Water:

| | | | | | | |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| | | | | | | |

Comment:

After reviewing the Operator supplied drone imagery, no stormwater erosion issues were observed.

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT