

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/07/2024

Submitted Date:

08/07/2024

Document Number:

716200340

**FIELD INSPECTION FORM**Loc ID 327409 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 47120

Name of Operator: KERR MCGEE OIL &amp; GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

18 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Oxy		ECMCInspections@Oxy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
429588	WELL	PR	05/01/2021	OW	123-35842	RAYMOND 38N-29HZX	PR
429589	WELL	PR	05/01/2021	OW	123-35843	RAYMOND 36N-29HZ	PR
429590	WELL	PR	12/01/2020	OW	123-35844	RAYMOND 15C-29HZ	PR
429592	WELL	PR	12/01/2020	OW	123-35845	RAYMOND 37N-29HZ	PR
429594	WELL	PR	12/01/2020	OW	123-35846	RAYMOND 15N-29HZ	PR
429595	WELL	PR	02/01/2023	OW	123-35847	RAYMOND 16N-29HZ	PR
429596	WELL	PR	11/01/2018	OW	123-35848	RAYMOND 38C-29HZ	PR

**General Comment:**

This is a routine audit of:

?Wellhead(s)

?Battery

?Drilling

?Fracking

Any corrective actions and associated dates from previous audits or inspections that have not been resolved remain in effect.

**Location**Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Pipe panels		
Corrective Action:		Date:	

**Equipment:**

Type: Plunger Lift	# 7		corrective date
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.201640,-104.799020
Comment:					
Corrective Action:					Date:

**Paint**

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	429588	Type:	WELL	API Number:	123-35842	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:		PR							
Corrective Action:						Date:			
<b>BradenHead</b>									
Date of Last Brhd Test:		02/28/2024		Annual Brhd Completed?		Yes			
Last Brhd Test Results		Initial Surf Csg Pressure:		19		Fluid Type: Water			
		End Surf Csg Pressure:		--					
Comment:		Plumbed to surface.							
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	429589	Type:	WELL	API Number:	123-35843	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:		PR							
Corrective Action:						Date:			
<b>BradenHead</b>									
Date of Last Brhd Test:		02/28/2024		Annual Brhd Completed?		Yes			
Last Brhd Test Results		Initial Surf Csg Pressure:		1		Fluid Type: Water			
		End Surf Csg Pressure:		--					
Comment:		Plumbed to surface.							
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	429590	Type:	WELL	API Number:	123-35844	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:		PR							
Corrective Action:						Date:			
<b>BradenHead</b>									
Date of Last Brhd Test:		02/28/2024		Annual Brhd Completed?		Yes			
Last Brhd Test Results		Initial Surf Csg Pressure:		1		Fluid Type: None			
		End Surf Csg Pressure:		--					
Comment:		Plumbed to surface.							
Corrective Action:						Date:			
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	429592	Type:	WELL	API Number:	123-35845	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:		PR							
Corrective Action:						Date:			



<b>BradenHead</b>		
Date of Last Brhd Test:	02/28/2024	Annual Brhd Completed? Yes
Last Brhd Test Results	Initial Surf Csg Pressure: 1	Fluid Type: None
	End Surf Csg Pressure: --	
Comment:	Plumbed to surface.	
Corrective Action:		Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments		
Comment	User	Date
<p>This is a routine audit of:</p> <p>?Wellhead(s)</p> <p>?Battery</p> <p>?Drilling</p> <p>?Fracking</p> <p>Any corrective actions and associated dates from previous audits or inspections that have not been resolved remain in effect.</p>	carlilec	08/07/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716200341	Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6655744">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6655744</a>